

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1	Anna Pl	108.12-8-17		1950	Ranch	1-story wood frame single family dwelling, low-pitched asphalt shingle side-gable roof w/ interior brick chimney, wood shingle siding, concrete block foundation, entrance & picture window recessed under roof on north end of front façade, single & paired double-hung windows, walk-in basement entrance & altered basement garage door opening on north façade.
2	Anna Pl	108.12-8-10		1954	Ranch	1-story brick masonry single family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney, gable dormers, brick wall construction, vinyl clapboard siding in upper gable ends, concrete foundation, wood frame wing on south end w/ vinyl clapboard siding, off center entrance flanked by casement bay windows, single & paired double-hung windows.
3	Anna Pl	108.12-8-16		1963	Ranch	1-story split level wood & brick masonry single family dwelling, asphalt shingle hip-gable roof w/ lower cross-gable roof & large exterior brick chimney on west end, brick wall construction & wood shingle siding, off center recessed entrance, large casement bay window, grouped casement windows, basement garage w/ double-doors, attached car port w/ upper deck on east end.
4	Anna Pl	108.12-8-11		1960	Ranch	1-story brick masonry single family dwelling, asphalt shingle hip-gable roof w/ large exterior brick chimney brick wall construction, concrete foundation, central recessed entrance, secondary entrance off of shed roof portico w/ round columns, solarium, bay window w/ brick corbels, single & paired double-hung windows, walk-in basement entrance & basement garage w/ sectional door on west facade.
5	Anna Pl	108.12-8-15.100		1970	Ranch	1-story brick masonry single family dwelling, asphalt shingle side-gable roof w/ two rear lower cross-gable s & large exterior brick chimneys on opposing ends, brick wall construction w/ vinyl clapboard siding in upper gable ends, center entrance off of gable portico w/ round columns, large multi-pane bay windows, paired double-windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
6	Anna Pl	108.12-8-8		1957	no style	<p>HOUSE: 2-story wood frame single family dwelling, asphalt shingle gable roof, vinyl clapboard siding, concrete foundation, side entrance on exterior vestibule, double-hung windows, oriel box windows on west facade.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle front-gable roof, vinyl clapboard siding, sectional garage bay door.</p>
7	Anna Pl	108.12-14		1972	Ranch	1-story brick masonry & wood frame single family dwelling, asphalt shingle side-gable roof w/ lower cross-gable front ell, brick wall construction, vinyl clapboard siding on upper gable ends & ell, concrete foundation, off center entrance, double-hung windows, casement windows, basement garage w/ sectional door on west facade.
8	Anna Pl	108.12-8-12.200		1989	Double Wide	1-story wood frame single family dwelling, low-pitched asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, center entrance off of porch w/ balustrades & turned columns, secondary entrance on south end, double-hung windows.
9	Anna Pl	108.12-8-13		1960	Ranch	1-story wood frame single family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, off center entrance, large picture window, single & paired double-hung windows, 1-bay basement garage.
10	Anna Pl	108.12-12.100		1988	Ranch	1-story wood frame single family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, off center entrance w/ partial sidelights, tripartite oriel window w/ brackets, double-hung windows, rear rear porch, 2-bay basement garage on west façade.
18	Apple View Ln	108.2-7-25.100	G. Graves (1875)	ca. 1870	Second Empire	3-story, 5-bay wood frame single-family dwelling, slate shingle Mansard roof w/ hip-dormers & paired interior brick chimneys on north & south ends, wood shingle siding, stone foundation, center hall entrance off of full porch w/ shingle sided columns & kneewalls, 2-story rear ell w/ brick chimney on interior east end, hip-dormers & enclosed side porch on ell's south side.
7	Birdsall Ave	108.12-2-25		ca. 1880	Greek Revival	2-story wood frame single-family dwelling, 2-bay front facade w/ enclosed porch w/ entrance off west end, asphalt shingle gable roof w/ central interior chimney, vinyl clapboard siding, stone & concrete foundation, enclosed side porch, attached 1-bay garage.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
10	Birdsall Ave	109.1-4-21	Marlboro Central High School	1936	Art Deco	2-story brick masonry school, flat roof of unknown synthetic material, brick wall construction, concrete foundation, double-door entrance on 2-story cast stone niches w/ cast stone relief sculpture, large replacement single & grouped metal frame windows, 2-story cast stone bay window w/ relief paneling, cast stone cornice, 2-story masonry addition on the south & rear w/ entrance.
18	Birdsall Ave	109.1-4-29.100	S. Berrian (1858) Camp Young	ca. 1858 ca. 1912	Greek Revival	HOUSE: 1.5-story, 3-bay wood frame single-family dwelling, asphalt-shingle cross-gable roof w/ brick chimneys on south & west ends, aluminum clapboard siding, stone foundation, side hall entrance w/ sidelights & transom off of full porch w/ later iron piers & balustrades, eyebrow & double-hung windows, 1-story wood frame rear addition. DORMITORY: 1.5-story wood frame multi-person dwelling, metal-shingle cross-gable roof, wood novelty & board-and-batten siding, stone & brick foundation, single & paired double-hung windows, 2 hanging track doors on east end, paired swinging doors on west ends of south & north sides. GARAGE: 1-story, 1-bay wide masonry garage, asphalt-shingle gable roof, concrete block construction, large garage door, entrance on west side, double-hung windows. SHED: 1-story wood frame shed w/ asphalt-shingle shed roof, board-and-batten siding. BARN FOUNDATIONS: Brick & stone foundations of former barns destroyed by arson in last few years.
48	Birdsall Ave	108.12-2-2		ca. 1850	Greek Revival	2-story ? style wood frame single-family dwelling, 3-bay front facade with side hall entry, asphalt-shingle gable roof w/ central brick chimney, vinyl clapboard siding, wrap-around porch w/ vinyl clapboard knee walls and square piers, single and paired double hung windows.
52	Birdsall Ave	108.12-2-3.100	Slack (1891)	1888	Classical Revival	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle gable roof, vinyl clapboard siding, brick & stone foundation, primary entrance under awning on 1-story south addition casement windows on lower story, double-hung windows on front facade's upper story, square bay windows on east façade. GARAGE: 1-story, 2-bay wide wood frame garage, asphalt shingle gable roof, aluminum siding.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
38	Bloom St	108.12-6-1		1957	Ranch	1-story brick masonry single-family dwelling, low-pitched asphalt shingle hip-gable roof w/ interior brick chimney, brick masonry construction, concrete foundation, off-center entrance, picture window, single & paired double-hung windows, 1-bay garage w/ sectional garage door.
39	Bloom St	108.12-7-29		ca. 1877	Second Empire	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle Mansard roof w/ segmental arch dormers & interior brick chimneys on south end, vinyl clapboard siding, stucco sided stone foundation, double-door side hall entrance off of full porch w/ chamfered columns, balustrades & paired eave brackets, upper story balcony w/ spindle balustrades, segmental arch double-hung windows, 1-story wing w/ Mansard roof on south, paired eave brackets & frieze panels, 2 rear entrances on exterior vestibules, shed roof attached garage w/ sectional door on north. WELL HOUSE: 1-story wood frame well house, metal hip-gable roof, shuttered openings.
69	Bloom St	108.12-5-5	W.C. (1875)	ca. 1875	Greek Revival	2-story wood frame single-family dwelling, 3-bay front facade w/ side hall entrance off of enclosed full porch, asphalt shingle gable roof, vinyl clapboard siding, stone foundation, double-hung windows, side deck w/ hooded entrance on rear east side, 1-story wood frame rear addition.
4	Brewster St	103.9-2-25	W. Farrington's Law Office (1858)	ca. 1875	Early Classical Revival	2-story wood frame two-family dwelling, 3-bay front facade w/ hooded side hall entrance, asphalt shingle gable gable, vinyl clapboard siding, stone foundation, double-hung windows, enclosed entrance toward rear on north side.
6	Brewster St	103.9-2-24	Res. of S.S. Howard (1858)	ca. 1850	Early Classical Revival	1-story wood frame single-family dwelling, 2-bay front facade w/ side entrance off of full porch, asphalt shingle gable roof w/ shed dormer and end chimney, vinyl clapboard siding, stucco sided foundation, double-hung windows, 2-story rear wood frame addition w/ side porch.
8	Brewster St	103.9-2-23	Lacy (1875)	ca. 1875	Early Classical Revival	HOUSE: 2-story wood frame single dwelling, 3-bay front facade w/ side hall entrance w/ transom off of full porch w/ balustrades and turned columns, asphalt shingle cross-gable roof w/ central brick chimney, vinyl clapboard siding w/ fish scale pattern wood shingles in front upper gable end, stone foundation. GARAGE: 1-story, 1-bay wide wood frame garage, asphalt shingle gambrel roof, vertical wood paneling.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
9	Brewster St	103.9-2-12.100	Res. W. Farrington (1858)	ca. 1858	Gothic Revival	HOUSE: 1.5 story wood frame single-family dwelling, 3-bay front facade, asphalt shingle cross-gable roof w/ brick chimney on south end, aluminum clapboard siding, stone foundation, double-hung & eyebrow windows, originally center hall entrance replaced w/ central front gable addition, entrance off of porch, 1-story additions on northwest corner & rear. GARAGE: 1-story, 3-bay wide wood frame garage, asphalt shingle shed roof, composite shingle siding.
10	Brewster St	103.9-2-27	I.S. Davis (1875)	ca. 1875	Early Classical Revival	2-story wood frame single-family dwelling, 5-bay front facade w/ center hall entrance off of full enclosed porch, metal side-gable roof w/ brick chimneys on opposing ends, asbestos shingle siding, stone foundation, double hung windows, entrance toward read on south side.
12	Brewster St	103.9-2-21.100	A. Brewster (1875)	ca. 1875	Early Classical Revival	HOUSE: 2-story wood frame single-family dwelling, 2-bay front facade w/ side hall entrance off of enclosed front porch w/ double-hung windows, asphalt shingle gable roof, stone foundation, double-hung windows enclosed porch on toward rear on south side. GARAGE: 1-story, 2-bay wide wood frame garage, asphalt shingle side-gable roof, vinyl clapboard siding.
10	Center St	108.4-2-34.500	C. Wygant (1875)	ca. 1875	Early Classical Revival	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle gable roof, vinyl clapboard siding, stone foundation, 1-story south wing, side hall entrance on east facade, double-hung windows, picture window on south, wrap-around porch w/ balustrades & piers. SHED: 1-story wood frame shed, asphalt shingle gable roof, wood clapboard siding.
9	Church St	108.12-7-4	J. Bonard (1875)	ca. 1870	Italianate	HOUSE: 2-story wood frame two-family dwelling, 5-bay front facade originally 3-bay wide w/ side hall entrance, double-hung windows, asphalt shingle gable roof w/ interior brick chimney, wood shingle siding, stone foundation, 2-story, 2-bay wide flat roof addition to west, small 1-story rear addition w/ secondary entrance, cornice w/ brackets. GARAGE: 1-story wood frame garage, folding doors & hanging track door, low pitched gable roof, novelty siding.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
10	Church St	108.12-1-20		ca. 1880	Queen Anne	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, brick foundation, side hall entrance, double-hung windows, walk-in basement, 2-story wrap-around porch w/ turned columns & balustrades.
12	Church St	108.12-1-21		ca. 1870	Gothic Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable w/ center gable wall dormer & interior chimney, composite shingle siding, stone foundation, center hall entrance off of shed roof porch with balustrades & piers, double-hung windows, eave brackets.
13	Church St	108.12-7-3		1889	Classical Revival	2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stucco sided stone foundation, side hall entrance off of hipped roof porch, secondary entrances on west side.
14	Church St	108.12-1-22		1888	Gothic Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ center gable wall dormer & interior chimneys, vinyl clapboard siding, stucco sided stone foundation, center double entrance off of shed roof porch, double hung windows.
16	Church St	108.12-1-29		ca. 1905	Colonial	1-story wood frame former garage, single-family family dwelling, asphalt shingle front-gable roof w/ interior brick chimney on north end, vinyl clapboard siding, concrete foundation, side entrance w/ partial sidelights off of gable portico supported by later iron piers, double-hung windows.
17	Church St	108.12-7-2		ca. 1891	Classical Revival	HOUSE: 2-story, 5-bay wood frame multi-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stucco sided stone foundation, center hall entrance off of gable portico w/ fishscale pattern wood shingle siding, double-hung windows, square bay window toward front on west facade, 2-story wood frame lean-to rear addition. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle front-gable roof, wood novelty siding, sectional garage bay doors, side entrance.
18	Church St	108.12-1-30		1881	Classical Revival	2-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone & concrete foundations, side hall entrance off of later porch, 1-story rear ell, 1-story wood frame addition on east, single & paired double-hung windows, single & grouped casement windows on upper story of front facade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
21	Church St	108.12-7-1.100		1915	Craftsman/Bungalow	<p>HOUSE: 1-story, 3-bay wood frame single-family house, asphalt shingle side-gable roof w/ interior brick chimney & shed wall dormer, wood clapboard & shingle siding, concrete block foundation, side entrance off of gable porch w/ tampered piers & balustrades, eave brackets & exposed rafter ends, double-hung windows, side entrance & paired double-hung windows on west facade, round bay window toward rear on east facade.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof w/ eave brackets, wood shingle siding, off center sectional garage bay door.</p>
28	Church St	108.12-1-36	Calvin Wygant	1890	Queen Anne	<p>2-story wood frame single-family dwelling, slate shingle complex-gable roof w/ interior brick chimney, vinyl clapboard siding, brick & stone foundation, double-door side hall entrance off of veranda w/ spandrels, balustrades & square columns, 2-story square bay window on southeast corner, 2-story cut-away bay window toward rear on south facade.</p>
36	Church St	108.12-1-37	J. Quimby (1875)	ca. 1875	Gothic Revival	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, roof extends over 2-story porch w/ turned columns & balustrades, side hall entrance, double-hung windows, 2-story tripartite bay window on south facade, veranda on southwest corner.</p> <p>GARAGE: 1-story wood frame garage, asphalt shingle cross-gable roof, vinyl clapboard siding, sectional garage bay door.</p> <p>POOL HOUSE: 1-story wood frame pool house, metal gable roof, vinyl clapboard siding, roof extends over open porch w/ French doors.</p>
37	Church St	108.12-8-1		ca. 1900	no style	<p>2-story wood frame multi-family dwelling, asphalt shingle cross-gable roof, vinyl clapboard siding, foundation of unknown material, side hall entrance, single & paired double-hung windows, secondary entrance on east façade, large 1-story attached masonry garage on front façade w/ sectional garage bay doors & small casement windows on west & east facades.</p>
40	Church St	108.12-1-39		1910	no style	<p>2-story wood frame single-family dwelling, asphalt shingle hip-gable roof, vinyl clapboard siding, foundation of unknown material, primary entrance on west end of 1-story addition on front facade w/ picture windows, secondary entrance on 1-story addition off northeast corner, paired casement windows.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
44	Church St	108.12-1-43		1910	Italianate	2-story, 3-bay wood frame two-family dwelling, low-pitched asphalt shingle hip-gable roof, vinyl clapboard siding, concrete foundation, center exterior vestibule entrance w/ hip-gable roof & later aluminum overhang, double-hung windows.
107	Church St	103.1-2-37	Milton Presbyterian Church	1899	Gothic	1-story wood frame church, asphalt shingle gable roof w/ lower cross hip-gable & side-gable, exterior brick chimney on east end, wood shingle siding, stone foundation, belfry tower w/ pyramidal roof on northwest corner w/ 2 pointed arch entrances under gable overhangs w/ gable trusses & brackets, arched entrance on east end, pointed arch double-hung windows, stained glass windows on tripartite apse end, large pointed arch stained glass windows w/ intersecting tracery on east & west ends.
108	Church St	103.9-1-3	W. Wooley (1875)	ca. 1875	Greek Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ exterior brick chimney, vinyl clapboard siding, brick & stone foundation, side hall entrance off of full porch w/ turned columns & later knee wall, double hung windows, 1-story wood frame wing on north w/ double hung windows, attached car port on south. BARN: 1-story wood frame carriage barn, asphalt shingle gable roof, vinyl clapboard siding, rail track doors on south facade, man door & multi-pane window on east facade.
112	Church St	103.9-1-5	Methodist Church & Cemetery (1875)	1812 1904-1905	Greek Revival	CHURCH: 1-story wood frame church, asphalt shingle side-gable roof w/ lower cross gable on front, vinyl clapboard siding, stone foundation, double-door entrance w/ fanlight off of gable portico at base of tower on southeast corner w/ belfry, large round arch stained glass windows w/ geometric tracery f& front facades, flanked by tall & narrow round arch stained glass windows on east, tall & w/ geometric tracery on west façade, narrow stained glass windows CEMETERY: Community cemetery, 400+ burials.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
115	Church St	103.1-2-34		ca. 1900	Colonial Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end, vinyl clapboard siding, stone foundation, center hall entrance off of 3-bay wide porch w/ round columns, off center rear entrance off of portico w/ round columns, side entrance w/ overhang on south end, double-hung windows. GARAGE: 1-story concrete block masonry garage, asphalt shingle front-gable roof, wood clapboard siding on upper gable ends, concrete block construction, sectional garage bay door.
117	Church St	103.1-2-35	Mrs. B.C. (1875)	1840	Greek Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower rear cross-gable & interior brick chimney, aluminum clapboard siding, stone foundation, side hall entrance off of gable portico w/ turned columns, double-hung windows, eyebrow windows, later 1-story rear addition. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle front-gable roof, wood shingle siding, sectional garage bay doors.
119	Church St	103.1-2-33	H. Stone (1875)	1847	Italianate	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ cupola & interior brick chimneys on opposing ends, wood clapboard siding, stone foundation, center hall entrance off of Classical style portico, full porch w/ round columns & balustrades on east façade, 2-story square bay window on west façade, double-hung windows, paired eave brackets. CARRIAGE HOUSE: 2-story wood frame carriage house, asphalt shingle side-gable roof w/ center gable wall .dormer, wood clapboard siding, rail track doors, double-hung window, round arch multi-pane windows on upper story, diamond shape dormer window.
	Dock Rd	108.4-3-19.100	Lattintown Creek Gorge	ca. 1850	industrial	
1	Dock Rd	103.9-1-36	J. Rowley (1875)	1860	Gothic Revival	2-story, 3-bay wood frame single-family dwelling, slate shingle side-gable roof w/ center gable wall dormer & brick chimney on end, vinyl clapboard siding, stone foundation, center hall entrance flanked by bay windows, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
9	Dock Rd	103.9-1-1	Luther Pratt (1858) J. Newman (1875)	1854	Italianate	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle cross-gable roof, vinyl clapboard siding, stucco sided stone foundation, double door side hall entrance off of wrap-around porch w/ later iron railing & supported by iron piers, double-hung windows, paired eave brackets, 1-story rear ell. CARRIAGE BARN: 1-story, 2-bay wood frame carriage barn, asphalt shingle cross-gable roof w/ cupola & weather vane, wood clapboard siding, board-and-batten siding in gable ends, double-hung windows, round arch double-hung windows in south & north gable ends. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, wood clapboard siding.
19	Dock Rd	103.9-1-32	M. Mahoney (1875)	ca. 1850	no style	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof, vinyl clapboard siding, concrete & stone foundation, original 2-story side-gable dwelling in rear, enclosed porch on front w/ later 2-story front-gable addition on front & original dwelling, double-hung windows, later oriel window flanked by small oculus windows BARN: 1-story wood frame barn w/ 1-bay attached garage in rear, metal gable roof, wood clapboard siding, stone foundation.
21	Dock Rd	103.9-1-30	S. Mackey (1875)	ca. 1850	Greek Revival	1-story, 3-bay wood frame multi-family dwelling w/ 1-story side wing to north, asphalt shingle side-gable roof, vinyl clapboard siding, brick foundation, side hall entrance off of porch, double-hung windows.
27	Dock Rd	103.9-1-29.100	H. Brown (1875)	ca. 1865	Greek Revival	2-story banked wood frame multi-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, 2 center entrances on lower story & entrances on opposing ends of front facade on upper story off of 2-story full porch w/ posts & balustrades replaced, double-hung windows.
33	Dock Rd	103.9-1-28	M. Smith (1875)	1809	Federal	3-story, 5-bay banked brick masonry single-family dwelling, common-bond brick walls, asphalt shingle side-gable roof w/ opposing interior brick chimneys, stone foundation, double-hung windows w/ stone lintels & sills, center hall entrance w/ sidelights, string course between upper stories, full porch removed.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
7	Dubois St	108.12-4-9		ca. 1820	Federal	2-story, 3-bay wood frame two-family dwelling w/ 1-story wings on west & east, asphalt shingle side-gable roof w/ brick end chimney & eave returns, vinyl clapboard siding, stucco sided stone foundation, side hall entrance w/ sidelights off of full porch w/ replacement piers & balustrades, secondary entrance w/ hood on east end.
9	Dubois St	108.12-4-8	W.B. (1875)	ca. 1820	Federal	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle hipped-gable roof w/ brick end chimney, vinyl clapboard siding, stucco sided stone foundation, center hall entrance w/ fluted pilasters & broken pediment, double-hung windows, 1-story rear addition w/ secondary entrance on west GARAGE: 1-story, 1-bay wood frame garage w/ asphalt shingle gable roof, vertical wood paneling.
10	Dubois St	108.12-3-26	Mrs. E. Doyle (1875)	ca. 1870	Italianate	2-story, 3-bay wood frame single-family dwelling, asphalt shingle hipped-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, center hall entrance, double-hung windows, secondary entrance on east off of full porch on w/ clapboard knee walls & tampered piers.
14	Dubois St	108.12-3-27		1947	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable dormers & exterior brick chimney, aluminum clapboard siding, concrete foundation, center exterior vestibule entrance, double-hung windows, secondary entrance on west off of gable roof porch, built-in garage w/ sectional door on east end.
21	Elliott Ln	108.2-6-31.100	J. Clark (1875)	ca. 1800	Federal	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys, vinyl clapboard siding, stone foundation, side hall entry off of enclosed full porch, originally 3-bay wide dwelling w/ later flat roof 2-story addition to south, 1-story addition on north side. SHED: 1-story wood frame shed, asphalt shingle gable roof, wood panel siding.
3	Grand St	108.12-3-52		ca. 1891	no style	2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof, asbestos shingle siding, stone foundation, center entrance off of full porch w/ turned columns, double-hung windows, 1-story rear shed roof addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
5	Grand St	108.12-3-51		ca. 1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stucco sided stone foundation, Originally 3-bay wide, side hall entrance off of porch w/ turned columns, 2-story, 1-bay addition to south.
6	Grand St	108.12-1-16		1880	Gothic Revival	2-story, 6-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ gable wall dormers & exterior concrete chimney, vinyl clapboard siding, stucco sided stone foundation, off set entrance off shed roof porch w/ replacement piers & balustrades, double hung windows.
9	Grand St	108.12-3-48		ca. 1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof, vinyl clapboard siding, concrete foundation, side hall entrance off of open porch w/ shed roof, double-hung windows.
10	Grand St	108.12-1-18		1912	Queen Anne	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, asbestos shingle siding, brick foundation, enclosed wrap-around porch w/ corner entrance & paired double-hung windows, double-hung windows.
11	Grand St	108.12-3-47	J. Bailey (1875)	ca. 1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney on south end, vinyl clapboard siding, concrete foundation, side hall entrance off of enclosed porch w/ side entrance on south, double-hung windows, eyebrow windows, 1-story rear addition.
14	Grand St		Marlboro Fire House	1976	Brutalist	2-story brick & concrete block masonry firehouse, flat roof of unknown synthetic material, brick & concrete block wall construction, concrete foundation, double-door entrance off of portico on south facade, 5 engine bay doors on east façade & 3 engine bay doors on west façade, 2-story niche windows, side entrance under overhang on west façade.
15	Grand St	108.12-3-44	J. Bailey (1875)	ca. 1875	Italianate	2-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, stucco sided stone foundation, side hall entrance off of full porch w/ turned columns, scroll sawn brackets, balustrades, oriel window, double-hung windows, summer porch toward rear on south, 1-story rear addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
17	Grand St	108.12-3-43	J. Dubois (1875)	ca. 1875	Italianate	2-story, 5-bay wood frame multi-family dwelling, preform metal shingle cross-gable roof, wood clapboard siding, brick & stone foundation, center double entrances off of full porch w/ turned columns & scroll sawn brackets, double-hung windows, small segmental arch windows in gable ends, paired eave brackets, 1-story addition off southeast corner.
19	Grand St	108.12-3-40		1880	no style	2-story, 2-bay brick masonry two-family dwelling, flat roof of unknown synthetic material, brick masonry walls, stucco sided stone foundation, side hall entrance off of later added portico porch w/ piers & balustrades, single & grouped double-hung windows w/ cast stone lintels & sills.
21	Grand St	108.12-3-40		1880	no style	2-story, 2-bay wood frame single-family dwelling, metal front-gable roof, wood shingle siding, stucco sided stone foundation, entrance of south end off of later porch, double-hung windows.
23	Grand St	108.12-3-39		1910	no style	2-story wood frame single family dwelling, asphalt shingle front-gable roof, vinyl novelty siding, brick & stone foundation, off center entrance on 2-story addition on front facade, single & paired double-hung windows, attached 1-story garage on north w/ sectional door, 1-story rear addition.
25	Grand St	108.12-3-38		1910	Four Square	2-story, 2-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ brick chimney, vinyl clapboard siding, stucco sided stone foundation, upper story w/ double-hung windows extends over porch w/ side entrance & casement windows, double-hung windows on south facade, 1-story rear addition w/ deck.
27	Grand St	108.12-3-37		1960	Ranch	1-story, 2-bay wood frame two-family dwelling, asphalt shingle front-gable roof w/ interior chimney on rear, vinyl clapboard siding, concrete foundation, side entrance w/ paired double-hung windows.
29	Grand St	108.12-3-36	L.C. (1875)	ca. 1860	Greek Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end, vinyl clapboard siding, stone foundation, side hall entrance off of full porch w/ replacement piers & balustrades, large picture window, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
30	Grand St	108.12-4-2	D.W. Kniffen (1875)	ca. 1875	Gothic Revival	HOUSE: 2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end, vinyl clapboard siding, stone foundation, side hall entrance off of porch w/ chamfered piers, scroll sawn brackets & balustrades, double-hung windows, 2-story, 1-bay addition on north end. GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof, vinyl clapboard siding.
32	Grand St	108.12-4-5		1880	Queen Anne	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ central interior brick chimney, vinyl clapboard siding, stone foundation, entrance off of later southeast corner deck, double-hung windows, later added casement windows on south side, later added rear porch.
33	Grand St	108.12-3-35	L.C. (1875)	1867	Italianate	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney at south end, vinyl clapboard siding, stone foundation, side hall entrance off of later full porch w/ turned columns, large picture window flanked by double-hung windows, double-hung windows, paired eave brackets.
36	Grand St	108.12-4-6		1948	Colonial Revival	1.5-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable wall dormers & exterior stone chimney, stone veneer & aluminum siding, concrete foundation, center entrance flanked by paired double-hung windows, half-round windows in upper gable ends, 1-story south side wing w/ single & paired double-hung windows, 1-story, 1-bay attached garage on north side, stone wall along street.
37	Grand St	108.12-3-32		ca. 1880	Gothic Revival	2-story, 3-bay wood frame two-family dwelling, asphalt shingle cross-gable roof w/ exterior chimney, vinyl clapboard siding, stucco sided stone foundation, side hall entrance, double-hung windows, 2-story rear addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
38-40	Grand St	108.12-4-30		ca. 1880	Gothic Revival	<p>HOUSE: 2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ gable wall dormer & interior brick chimney, aluminum clapboard siding, brick foundation stucco sided stone foundation, side hall entrance, full porch w/ turned columns, scroll sawn brackets, spandrels & replacement iron balustrades, double-hung windows, square bay window on south side, 1-story rear addition w/ secondary entrance on west, paired brackets in gable peaks, later 2-story rear addition.</p> <p>CARRIAGE HOUSE: Former 1-story, 3-bay wood frame carriage house w/ asphalt shingle side-gable roof w/ gable wall dormer, vinyl clapboard siding, stone foundation, center entrance off of concrete deck, double-hung windows, octagonal oculus.</p>
39	Grand St	108.12-3-31		ca. 1880	Classical Revival	2-story, 3-bay banked wood frame single-family dwelling, asphalt shingle side-gable roof with exterior brick chimney, aluminum clapboard siding, stone foundation, side hall entrance off of open full porch w/ turned columns, later picture window flanked by double-hung windows, double-hung windows.
41	Grand St	108.12-3-29		ca. 1880	Classical Revival	2-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof, vinyl clapboard siding, concrete foundation, side hall entrance off of full w/ paired double-hung windows on front facade, double-hung windows on north & south facades, tripartite oriel window toward rear on south facades.
42	Grand St	108.12-4-29		ca. 1880	Gothic Revival	2-story, 3-bay frame single-family dwelling, asphalt shingle side-gable roof w/ gable wall dormer, rear shed dormer, interior brick chimney, vinyl clapboard siding, patterned wood shingle siding in upper gable ends, stucco sided stone foundation, side hall entrance off of full porch w/ turned columns & balustrades, double-hung windows, square bay window on south side, 2-story rear addition.
45	Grand St	108.12-3-28		ca. 1900	Queen Anne	2-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof, vinyl clapboard siding, concrete foundation, side hall entrance off of full w/ paired double-hung windows on front facade, double-hung windows on north & south facades, tripartite oriel window toward rear on south facades.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
46	Grand St	108.12-4-26		1929	Bungalow/Craftsman	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on south end, wood shingle siding w/ lower vinyl clapboard siding, concrete foundation, center entrance off of gable porch w/ recessed columns atop of tapered masonry piers & balustrades, single & paired double-hung windows, square bay windows on south & north facades, eave brackets.
50	Grand St	108.12-4-25	J. Staples (1875)	ca. 1875	Greek Revival	HOUSE: 2-story, 3-bay wood frame & brick masonry two-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on south end, aluminum clapboard siding on upper story & later brick wall construction on lower story, brick & stone foundation, side hall entrance w/ picture window & double-hung windows on front façade, later 2-story rear addition. SHED: 1-story wood frame shed w/ attached car port.
51-55	Grand St	108.12-4-7.100	Presbyterian Church (1875)	1870	Romanesque	CHURCH: 1-story, 3-bay brick masonry church, slate shingle gable roof w/ interior brick chimney on south side, brick wall construction, brick & stone foundation, center belfry tower w/ slate shingle cross-gable roof & small spire, round arch center double-door entrance w/ fanlight flanked by round arch double-door side aisle entrances, tall round arch windows above front façade entrances, series of tall round arch stained glass windows on north & south facades, double-hung basement windows in segmental arch openings on north façade, corner wall buttresses on front façade, rear double-door entrance off of car port, brick corbelling around tower & underneath eave, wall buttresses on front façade. PARISH HALL: 1-story, 5-bay concrete block masonry parish hall, asphalt shingle side gable roof, concrete block wall construction, clapboard siding on upper gable ends, center entrance on exterior vestibule, paired casement windows. SHED 1: 1-story, 1-bay wood frame shed, asphalt shingle side-gable roof, wood panel siding, double-door entrance on west side. SHED 2: 1-story, 1-bay wood frame shed, asphalt shingle gambrel roof, wood panel siding, double-door entrance on south end.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
52	Grand St	108.12-4-24		ca. 1892	Queen Anne	2-story, 2-bay wood frame two-family dwelling, asphalt shingle cross-gable roof w/ exterior concrete chimney, vinyl clapboard siding, stucco sided stone foundation, 3-story corner tower w/ high-pitched pyramidal hip roof. side-hall entrance off of full porch w/ turned columns & scroll sawn brackets, single & paired double-hung windows, square bay windows on south & north facades.
54	Grand St	108.12-4-23		1960	Ranch	2-story masonry & wood frame multi-family dwelling, low-pitched asphalt shingle hip-gable roof w/ exterior brick chimney, lower story stone veneer & upper story brick veneer on front façade, vinyl clapboard siding, concrete foundation, center entrance w/ grouped double-hung windows, upper sliding doors on balcony over double garage bay doors on front façade, secondary entrance w/ single & paired double hung windows on south façade, double-hung windows on north façade.
62	Grand St	108.12-5-2	Mrs. W. (1875)	ca. 1870	Classical Revival	1.5-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance off of full porch, double-hung windows, eyebrow windows, 1-story hipped-gable wing on south & 1-story gable wing on north.
64	Grand St	108.12-5-3	P. Crow (1875)	ca. 1870	Classical Revival	HOUSE: 1.5-story, 3-bay wood frame single-family dwelling, metal side-gable roof w/ exterior chimney on north side, vinyl clapboard siding, stone foundation, side hall entrance off of full enclosed porch, double hung windows, eyebrow windows, 1-story wing on south w/ casement windows. CARRIAGE HOUSE: 2-story wood frame converted carriage barn, asphalt shingle side-gable roof, board-and-batten siding, double door entrance with shed overhang, double-hung windows, later deck & stairs on south side.
66	Grand St	108.12-5-4		1985	Ranch	1-story wood frame single-family dwelling, low-pitched asphalt shingle cross-gable roof w/ exterior brick chimney on north side, vinyl clapboard siding, concrete foundation, primary entrance off of portico on south facade, double-hung windows, decorative bargeboards.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
71	Grand St	108.12-5-6	St. Mary's R. C. Church Rectory	1960	Ranch	1-story banked brick masonry rectory, asphalt shingle side-gable roof w/ interior brick chimney, brick wall construction w/ some vinyl clapboard siding on north end & east façade, concrete foundation, recessed entrance w/ sidelight & flanked by large pane & casement windows, recessed entrance w/ grouped casement windows on north end, enclosed upper story deck on east façade.
73	Grand St	108.12-5-6	St. Mary's R. C. Church Parish House	1960	Modern	CHAPEL: 1-story brick & stone masonry chapel, low-pitched asphalt shingle roof w/ exterior brick chimney, brick & stone wall construction, concrete foundation, recessed double-door entrance w/ sidelights & transom on stone-veneer entry wing on north, lower 1-story rear wing w/ single pane windows. GARAGE: 1-story, 3-bay metal frame garage, metal front-gable roof, metal siding, 3 sectional garage bay doors.
76	Grand St	108.12-5-22	W. Dubois (1875)	ca. 1860	Classical Revival	3-story banked wood frame two-family dwelling, metal side-gable roof w/ interior brick chimneys on opposing ends, aluminum clapboard siding, stucco sided stone foundation, 2 off set entrances on 1st story & 2nd story off of 2-story porch basement & 1st story off of 2-story replacement porch w/ piers & balustrades, double-hung windows, entrance toward rear on south side.
84	Grand St	108.12-5-21	J. Hepworth (1875)	ca. 1880	Queen Anne	2-story, 3-bay wood frame single-dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, side hall entrance off of full porch w/ replacement piers & balustrades, double-hung windows, tripartite bay window toward rear on south side.
85	Grand St	108.12-5-15		1952	Cape Cod	1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower cross-gable & interior brick chimney, wood shingle siding, concrete foundation, gable bump-out w/ grouped double-hung windows & primary entrance toward rear on north façade, single double-hung windows, picture window & secondary entrance on south façade.
88	Grand St	108.12-5-18	J. Hepworth (1875)	1870	Queen Anne	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof with interior brick chimney, wood clapboard siding, stone foundation, side hall entrance off of wrap-around porch w/ turned columns, scroll sawn brackets, & balustrades, large picture window flanked by double-hung windows, double hung windows, granite stone retaining wall.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
91	Grand St	108.12-5-16		1957	Ranch	1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete chimney on south end, vinyl clapboard siding, concrete foundation, off-center entrance, single & paired double-hung windows, 1-story attached 1-bay garage w/ asphalt shingle side-gable roof & large sectional garage bay door.
94	Grand St	108.4-6-29.211		2008	no style	2-story, 4-bay wood frame two-family house, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, two separate center entrances off of deck, side entrance toward rear off of deck & walk-in basement entrance on north facade, double-hung windows.
95	Grand St	108.12-5-17		1959	Ranch	HOUSE: 1-story banked brick masonry single-family dwelling, low-pitched asphalt shingle side-gable roof w/ exterior brick chimney on south end, brick wall construction, concrete foundation, off-center entrance, recessed side entrance toward north end of front facade, single & paired double-hung windows, picture window & casement window on front facade. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle side-gable roof, vinyl clapboard siding, two sectional garage bay doors.
3	Hallock Dr	103.3-2-24.100	J. Ball Foundry Site	ca. 1850	industrial	
171	Highland Ave	108.4-7-22	A.J. Berrian (1875)	ca. 1870	Classical Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on south, aluminum clapboard siding, stucco sided stone foundation, side hall entrance off of full porch w/ turned columns & iron balustrades, double-hung windows, 2-story side wing w/ oriel window & secondary entrance on south end. GARAGE: 1-story, 1-bay wood frame garage w/ asphalt shingle gable roof & aluminum clapboard siding.
193	Highland Ave	108.4-2-40		ca. 1890	Classical Revival	HOUSE: 2.5-story wood frame single-family dwelling asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, side hall entrance off of enclosed wrap-around porch w/ casement windows, double-hung windows, 2-story shed roof addition on north side. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, vinyl clapboard siding.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1	Hudson Ter	108.12-1-35		1955	Cape Cod	1-story brick masonry single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, brick wall construction, vinyl clapboard siding in upper gable ends, concrete block foundation, off center entrance w/ single double-hung windows & picture windows on front facade, small 1-story brick wing on north end w/ paired casement windows, picture & single double-hung windows on south facade, 1-bay basement garage.
2	Hudson Ter	108.12-1-5.200		1991	Cape Cod	1-story wood frame single-family dwelling, asphalt shingle side gable roof w/ large gable dormer on rear, vinyl clapboard siding, concrete foundation, sliding door entrance on south wing off of deck casement windows.
4	Hudson Ter	108.12-1-5.100		1988	Manufactured	HOUSE: 1-story wood frame single-family dwelling, low-pitched asphalt shingle gable roof, wood sheet siding, off center entrance, double-hung windows, double-door entrance off of rear deck. SHED: 1-story wood frame shed w/ asphalt shingle roof & vinyl clapboard siding.
6	Hudson Ter	108.12-1-42.200		2004	Colonial	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior chimney on north end, vinyl clapboard siding, concrete foundation, center hall entrance w/ partial sidelights, double-hung windows, rear deck. SHED: 1-story wood frame shed w/ asphalt shingle gable roof, vinyl clapboard siding, double-hung window, & double-door entrance.
8	Hudson Ter	108.12-1-42.100		ca. 1880	Classical Revival	2 story, 3 bay wood frame single dwelling, asphalt shingle gable roof w/ interior center brick chimney, vinyl clapboard siding, stone foundation, side hall entrance off of concrete stoop w/ iron railings & overhang, double-hung windows, later picture window, 1-story rear addition w/ concrete block chimney.
10	Hudson Ter	108.12-1-41		ca. 1910	Queen Anne	HOUSE: 2-story wood frame single family house, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, entrance off of veranda w/ balustrades, turned columns, scroll sawn brackets & spandrels, double-hung windows. GARAGE: 1-story wood frame garage, asphalt shingle gable roof, board-&batten siding, sectional garage bay door, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
12	Hudson Ter	108.12-1-40		ca. 1880	Queen Anne	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney & gable dormer, vinyl clapboard siding, stucco sided stone foundation, side hall entrance off of full porch, 1-story wing on south side w/ secondary entrance. GARAGE: 1-story, 1-bay wood frame garage w/ asphalt shingle gable roof & vinyl clapboard siding.
14	Hudson Ter	108.12-1-38		ca. 1890	Queen Anne	2-story, 3-bay wood frame single dwelling, asphalt shingle side-gable roof w/ interior brick chimney on north end & later added center project gable overhang over 2-story porch, center entrance on lower & upper stories, aluminum clapboard siding, stone foundation, double-hung windows, tripartite bay window on south side, oriel window on north side, paired eave brackets, 1-story rear addition & porch.
18	Hudson Ter	108.12-8-2		1881	Gothic Revival	HOUSE: 2-story, 5-bay wide wood frame dwelling, asphalt shingle side-gable roof w/ gable wall dormers & two opposing interior brick chimneys, wood clapboard siding, stone foundation, center entrances w/ sidelights on front & rear off of porticos w/ turned columns & upper balconies, double-hung windows, later 1-story concrete block wing on north w/ upper balustrades. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle roof, wood clapboard siding.
19	Hudson Ter	108.12-7-41.100		2003	Cape Cod	1-story wood frame single-family dwelling, asphalt shingle complex-gable roof w/ gable dormer, wood shingle siding, concrete foundation, off center entrance flanked by paired double-hung windows w/ transoms, single double-hung windows w/ transoms on north facade, basement garage w/ sectional door toward rear on north facade.
21	Hudson Ter	108.12-7-37		1923	Dutch Colonial Revival	2-story, 3-bay wood frame single dwelling, asphalt shingle gambrel roof w/ large shed dormers & exterior brick chimneys, wood clapboard siding, stone foundation, center hall entry w/ sidelights & fanlight transom off of arched portico w/ turned columns, double-hung windows, quarter round windows, former 1-story attached garage with gable dormers on south side, 1-story hipped roof wing on south side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
24	Hudson Ter	108.12-8-3.100		1883	Queen Anne	HOUSE: 2-story, 3-bay wood frame single dwelling, asphalt shingle cross-gable roof, asbestos shingle, stone foundation, side hall entrance off of full porch, double-hung windows, square bay window toward rear on south side, paired eave brackets. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, vinyl clapboard siding.
25	Hudson Ter	108.12-7-36		1925	Craftsman Cottage	1-story, 2-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ interior brick chimney, vinyl clapboard siding, concrete foundation, side entrance off of porch w/ round columns & grouped double-hung windows on front facade, double-hung windows, square oriel window on north facade, walk-in basement & garage on rear facade.
26	Hudson Ter	108.12-8-3.200		1997	Colonial	HOUSE: 2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, center hall entrance w/ sidelights, single & paired double-hung windows, secondary entrance & sectional garage bay door w/ overhang on south end. SHED: 1-story wood frame shed w/gable roof, wood novelty & aluminum clapboard siding, concrete foundation, 2 sectional garage bay doors, haymow door on south end, double-hung windows.
27	Hudson Ter	108.12-7-34		ca. 1900	Queen Anne	HOUSE: 2-story wood frame single family dwelling, asphalt shingle side-gable roof w/ interior brick chimney & lower cross-gables on front & rear, aluminum clapboard siding, stone foundation, side-hall entrance off of full porch w/ turned columns & balustrades, double-hung windows, 1-story addition on south end, rear entrance & casement windows on rear ell. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle cross-gable roof, wood novelty & aluminum clapboard siding, concrete foundation, 2 sectional garage bay doors, haymow door on south end, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
28-30	Hudson Ter	108.12-8-4		ca. 1900	Queen Anne	<p>HOUSE 1: 2-story, 3-bay wood frame multi-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney on south end, composite clapboard siding, stone foundation, double-door center hall entrance off of full porch w/ round columns on square piers & later balustrades, single, paired, & grouped double-hung windows, tripartite bay window on south façade.</p> <p>HOUSE 2: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof, composite clapboard siding, stone foundation, entrance on center exterior vestibule, double-hung windows.</p>
31	Hudson Ter	108.12-7-33		1880	Queen Anne	<p>HOUSE: 2-story wood frame two-family dwelling, asphalt shingle gambrel roof w/ lower cross-gable & interior brick chimney, aluminum clapboard siding, brick foundation, entrance w/ overhang off of patio on south end, rear stairs accessing upper story deck & entrance w/ shed overhang, ornate dormers on front & rear, tripartite bay window on east façade.</p> <p>CAR PORT: 1-story wood frame car port w/ asphalt shingle gable roof & vinyl clapboard siding in gable ends.</p>
32	Hudson Ter	108.12-8-5	W.H. Purdy (1875)	1864	Second Empire	2-story, 3-bay wood frame single dwelling, slate shingle Mansard roof w/ dormers & exterior brick chimneys, vinyl clapboard siding, stone foundation, double door side hall entrance w/ transom off of full porch w/ chamfered piers, scroll sawn brackets & balustrades, double-hung windows, tripartite bay toward rear on north side, paired eave brackets & cornice panels, 1-story, flat roof addition on south side w/ secondary entrance & picture window.
33	Hudson Ter	108.12-7-32.110		1930	Craftsman Cottage	1 story, 3 bay wood frame single dwelling, asphalt shingle hipped roof w/ exterior brick chimney, vinyl clapboard siding, wood novelty siding on front facade, concrete foundation, roof extends over full front porch w/ center entrance, double-hung windows, enclosed rear porch.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
34	Hudson Ter	108.12-8-6.110	Mrs. Lawrence (1875)	ca. 1875	Classical Revival	HOUSE: 2-story, 3-bay wood frame single dwelling, asphalt shingle side-gable roof w/ exterior brick chimney, vinyl clapboard siding, stone foundation, double door side hall entrance off of full porch, double-hung windows, 1-story rear addition w/ secondary entrance off of full porch w/ turned columns & balustrades, double-hung windows, half round windows in upper gable ends, 1-story wood frame addition on south end, rear entrance & casement windows on 1-story rear ell. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle cross gable roof,
35	Hudson Ter	108.12-7-32.120		1930	Craftsman Cottage	1 story, 3 bay wood frame single dwelling, asphalt shingle hipped roof w/ exterior brick chimney, vinyl clapboard siding, wood novelty siding on front facade, concrete foundation, roof extends over full front porch w/ center entrance, double-hung windows, enclosed rear porch.
36	Hudson Ter	108.12-8-6.210		1992	Colonial	1-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, off center entrance w/ sidelights, single & paired double-hung windows, casement windows on upper story, secondary entrance on south end.
37	Hudson Ter	108.12-7-32.130		1930	Craftsman Cottage	1 story, 3 bay wood frame single dwelling, asphalt shingle hipped roof w/ exterior brick chimney, vinyl clapboard siding, wood novelty siding on front facade, concrete foundation, roof extends over full front porch w/ center entrance, double-hung windows, enclosed rear porch.
39	Hudson Ter	108.12-7-32.140		1930	Craftsman Cottage	1 story, 3 bay wood frame single dwelling, asphalt shingle hipped roof w/ exterior brick chimney, vinyl clapboard siding, wood novelty siding on front facade, concrete foundation, roof extends over full front porch w/ center entrance, double-hung windows, enclosed rear porch.
40	Hudson Ter	108.12-8-7.100		1992	Raised Ranch	1-story masonry & wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding & brick wall construction, concrete foundation, center hall entrance off of deck onto mid-floor interior landing, double-hung windows, oriel w/ casement windows, 2- bay basement garage w/ sectional doors on north end.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
41	Hudson Ter	108.12-7-30		ca. 1880	Second Empire	2 story, 3 bay banked wood frame two-family dwelling, slate shingle mansard roof w/ exterior brick chimneys & dormers, wood clapboard siding, brick foundation, double-door side hall entrance w/ transom off of full porch w/ chamfered column & scroll sawn brackets, double-hung windows, 3-story tripartite bay windows w/ eave brackets on south facade, rear double-door entrance w/ transom off of 2-story rear porch w/ chamfered columns, scroll sawn brackets & balustrades, cornice panels & brackets, walk-in basement entrance, later attached concrete block garage w/ double doors.
42	Hudson Ter	108.12-8-7.300		1950	Cape Cod	HOUSE: 1-story, 3-bay brick masonry single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney & gable dormers, brick wall construction w/ vinyl clapboard siding in upper gable ends, concrete foundation, center entrance on exterior vestibule flanked by oriel window & paired double-hung window, double-hung dormer windows. GARAGE: 1-story, 1-bay concrete block masonry garage, asphalt shingle front-gable roof, wood panel siding in upper gable end, sectional garage bay door w/ overhang. SHED: 1-story wood frame shed w/ double doors.
44	Hudson Ter	108.12-8-9		1920	Bungalow/Craftsman	1-story wood frame single-family dwelling, asphalt shingle clipped-gable roof w/ interior brick chimney & gable dormers, vinyl clapboard siding, stucco sided foundation, center hall entrance w/ partial sidelights off of gable roof portico flanked by double-hung picture windows, clipped gable wing w/ paired & grouped double-hung windows.
52	Hudson Ter	108.12-8-18.100		2017	Ranch	1-story wood frame single-family dwelling, asphalt shingle complex hip-gable roof, wood shingle in upper gable ends, vinyl clapboard siding, lower stone veneer & around recessed entrance, single & paired double-hung windows.
62	Hudson Ter	108.12-8-19		2018	Ranch	1-story wood frame single-family dwelling, asphalt shingle cross-gable roof, vinyl clapboard siding, concrete foundation, single & paired double-hung windows.
65	Hudson Ter	108.12-6-24		1960	Ranch	1-story brick masonry single-family dwelling, low-pitched asphalt shingle hip-gable roof, brick wall construction, concrete foundation, off center entrance, large picture window, single & paired double-hung windows, integrated 1-bay garage w/ sectional door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
66	Hudson Ter	108.12-8-20		1962	Ranch	1-story brick masonry & wood frame single-family dwelling, asphalt shingle cross hip-gable roof w/ exterior brick chimney, brick wall construction & vinyl clapboard siding, concrete foundation, center entrance flanked by large picture windows, later attached 2-story gable ell w/ large picture window over 1-bay garage with sectional door.
70	Hudson Ter	108.12-8-22	Dr. E.P. Bailey (1891)	1890	Queen Anne	HOUSE: 2-story, 4-bay wood frame single dwelling, asphalt shingle front gable roof w/ exterior brick chimney, wood clapboard siding, stone foundation, side hall entrance off of full porch w/ turned columns, balustrades, & spandrels, double-hung windows, 2-story tripartite bay toward rear on south side w/ mansard roof. GARAGE: 1-story wood frame converted barn, asphalt shingle gable roof w/ brick chimney, wood novelty siding, attached garages.
71	Hudson Ter	108.12-6-23.500		2009	Colonial	2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ projecting gable wall dormers, vinyl clapboard siding, concrete foundation, center hall entrance w/ partial sidelights off of full shed roof porch w/ round columns & balustrades, double-hung windows, large half-round window, 1-story attached garage on north w/ 2 sectional garage bay doors.
74	Hudson Ter	108.12-8-1		1960	Ranch	1-story brick masonry single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney, brick wall construction w/ vinyl clapboard siding on upper gable ends, concrete foundation, off center entrance w/ picture & bay windows on front facade, side entrance flanked by double-hung windows on north end, basement garage w/ sectional door on south end.
8	Hudson Way	109.1-3-14.200	C. Cover (1875)	ca. 1875	Classical Revival	2-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on east end, vinyl clapboard siding, stone foundation, double-hung windows, 2-story tripartite bay windows toward rear on west side, several later 1 & 2-story additions.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
36	James St	109.1-4-65	J. Shaw (1875)	ca. 1875	Queen Anne	<p>HOUSE 1: 2-story- 4-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, brick foundation, off center entrance under gable hood on west facade, double-hung windows, /3-story porch w/ scroll sawn brackets & clapboard knee walls on east facade, 1-story wing on south w/ hipped roof, north wing w/ garage.</p> <p>HOUSE 2: 1-story wood frame single-family dwelling w/ attached 2-bay garage, low-pitched asphalt shingle gable roof w/ stone chimney, vertical wood siding, concrete foundation, center entrance, large pane windows w/ casement transoms.</p> <p>HOUSE/GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof, vinyl clapboard siding.</p>
44	James St	109.1-4-64	T. Shipton (1875)	ca. 1875	Second Empire	<p>HOUSE: 2-story wood frame two-family dwelling, asphalt shingle Mansard roof w/ exterior brick chimney & dormers, asbestos shingle siding, stone foundation, off center entrance on east facade off of full porch w/ chamfered piers, paired scroll sawn brackets & balustrades, off center entrance w/ transom on south facade off of partial porch w/ chamfered piers & paired scroll sawn brackets, double-hung windows, paired upper story double-hung windows on east facade, 2-story tripartite bay windows on south facade, scroll sawn eave brackets.</p> <p>BARN: 1-story wood frame barn, asphalt shingle side-gable roof, board-and-batten siding, stone foundation, off-set double doors.</p> <p>WELL HOUSE: 1-story wood frame well house, asphalt shingle roof, asbestos shingle siding, stone foundation.</p> <p>GARAGE: vinyl clapboard siding in upper gable ends, 1-story stucco sided masonry garage, asphalt shingle side-gable gable roof, off center entrance, 2 garage doors.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
62-80	James St	109.1-4-71		ca. 1900	Queen Anne	<p>HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney on south end, vinyl clapboard siding, concrete foundation, entrance off of enclosed porch w/ double-hung windows, rear entrance off of small gable portico, double-hung windows. BARN: 2-story wood frame, wood novelty siding, low-pitched asphalt shingle gable roof, concrete foundation, barn doors & man door on east façade, double-hung & multi-pane windows.</p> <p>GARAGE: 1-story masonry garage, asphalt shingle gable roof, concrete block construction vinyl clapboard siding on upper gable ends, large sectional garage door.</p>
1	King St	108.12-3-13		1920	Commercial	2-story brick masonry commercial building, asphalt shingle hip-gable roof w/ hip-gable dormer & exterior brick chimney on rear, brick wall construction, stone foundation, commercial front include center recessed center entrance flanked by large plate glass windows under awning, grouped double-hung windows on upper story of front façade, single & paired double-hung windows on north & south facades.
7	King St	108.12-3-18	D. Wygant (1875)	ca. 1875	Classical Revival	2-story, 3-bay wood frame two-family dwelling, flat roof of unknown synthetic material, vinyl clapboard siding, stone foundation, dwelling widens forward rear, side hall entrance framed by architrave & pilasters, secondary entrance off of recessed porch, 2-story square bay windows on north façade, double-hung windows, cornice paneling.
11	King St	108.12-3-22	J. Hepworth (1875)	ca. 1815	Federal	2-story, 3-bay banked brick masonry two-family dwelling w/ small 2-story wing on south, metal side-gable roof w/ 2 interior brick chimneys on south end, brick wall construction, stone foundation, side hall entrance w/ architrave & pilasters off of full 2-story porch w/ square columns, flat sawn balustrades & brackets, walk-in basement entrance, double-hung windows, half round window in upper gable end on south, 2-story wood frame rear addition, metal roof on south wing w/ interior brick chimney on south end, brick wall construction, stone foundation, off center entrance & double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
38-40	Mahoney Rd	103.1-1-63.100	J. Kaley (1875)	ca. 1870	Classical Revival	<p>HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ rear shed dormer, aluminum clapboard siding, stone foundation, center hall entrance off of partial porch, double-hung windows, secondary entrance on west side & on east side off of side porch.</p> <p>SHED: 1-story, 1-bay wood frame shed, asphalt shingle gambrel roof, vertical wood panel siding.</p>
64	Mahoney Rd	95.4-2-29	H. Filler (1875)	ca. 1870	Classical Revival	<p>HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior chimney on west end, wood novelty siding, stone foundation, off center entrance off of fill porch w/ turned columns, and concrete deck, double-hung windows, secondary entrance off of 1-story addition toward rear on west side.</p> <p>SHED: 1-story wood frame shed, asphalt shingle gambrel roof, vertical wood siding, center double-door entrance flanked by small casement windows.</p>
71	Mahoney Rd	103.1-1-46	J. Ransley (1875)	ca. 1875	no style	<p>HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney & exterior concrete block chimney, vinyl clapboard siding, stone foundation, sliding door entrance on east end of later 1-story addition on front facade, double-hung windows.</p> <p>BARN: 1-story, wood frame barn, asphalt shingle gable roof, wood novelty siding, stone foundation, barn rail doors, double-hung windows, loft rail door on east gable end.</p>
118	Mahoney Rd	95.4-2-22	J. Mackie (1858)	ca. 1850	Classical Revival	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ exterior rear brick chimney, vinyl clapboard siding, stone foundation, side hall entrance w/ transom off of full porch w/ scroll sawn brackets, turned columns, & balustrades, double-hung windows.</p> <p>GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof w/ exterior brick chimney on north end, wood shingle siding in upper gable end, sliding garage doors.</p> <p>SHED: 1-story wood frame shed, flat roof, wood clapboard siding, double-hung windows.</p> <p>FOUNDATION: Foundation of former barn near roadway, lower story framing & novelty siding on east and north sides.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
12-14	Main St	103.9-2-20	St. John's Catholic Church & Rectory	1876 1935	Gothic	CHURCH: 1-story, 3-bay brick masonry & wood frame church, asphalt shingle gable roof w/ brick exterior chimney on north, center tower w/ belfry, lantern & spire, brick wall construction on front façade & vinyl clapboard siding on north & south façade, stone foundation, double-door center & side entrance w/ cast stone lintels, statuary niche over center entrances, mall pointed-arch stain glass windows, pointed-arch stained glass windows on north & south facades. RECTORY: 2-story wood frame rectory, asphalt shingle hip-gable roof, wood shingle siding, stone foundation, entrance under hip-gable overhang & square bay window on south façade, double-hung windows, later enclosed upper story porch on southwest corner.
25	Main St	103.9-2-36	O.B. Whitney (1875)	ca. 1875	Gothic Revival	2-story, 5-bay wood frame two- dwelling, asphalt shingle side-gable roof w/ center gable wall dormer & interior brick chimney on east end, asbestos shingle siding, stone foundation, center hall entrance & later second family entrance off of later partial porch, side entrance to enclosed exterior stairwell to upper story, double-hung windows, eave returns & brackets, cornice panels.
30	Main St	103.9-2-28	First National Bank	1910	Commercial	2-story brick masonry commercial building, flat roof of unknown synthetic material, brick wall construction, stone foundation, frontfront consists of recessed double-door entrance, large multi-pane windows & transoms, double-hung windows on upper story, brick niches beneath stepped parapet wall, caststone date plaque.
32	Main St	103.9-2-26	J. Miller (1875)/Miller Dry Goods	ca. 1880	Commercial	2-story brick masonry commerical building, slate shingle Mansard roof w/ gable wall dormers & large stepped gable wall dormer, brick wall construction, stone foundation, center entrance w/ stained glass sidelights accessing the upper stories flanked by 2 storefronts, storefronts included horizontal plate glass windows w/ color glass transoms, a recessed entrance w/ large transom & flush double-door entrance w/ large plate glass windows. double-hung windows on upper story & half-round double-hung windows on dormers, square oriel window w/ brackets & sided in vinyl clapboard & wood shingle.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
33	Main St	103.9-2-37	J.P. Townsend (1875)	ca. 1870	Gothic Revival	HOUSE: 2-story, 3-bay wood frame two-family dwelling, asphalt shingle low-pitched gable roof w/ center gable wall dormer, vinyl clapboard siding, stucco sided stone foundation, double-door center hall entrance flanked by octagonal windows, double-hung windows, center upper story double-hung window flanked by smaller narrower windows w/ hood molds. BARN: 2-story wood frame barn, gable roof, exterior plywood siding, single door entrance on south side, 2 bay door entrances on east side.
56-58	Main St	103.9-2-10	Sarah Hull Hallock Free Library	1924	Colonial Revival	1-story, 3-bay wood frame library, asphalt shingle hip-gable roof w/ exterior brick chimney on rear, wood clapboard siding, stucco sided stone foundation, center entrance w/ fanlight off of hip-gable roofed portico w/ round columns & flanked by paired double-hung windows w/ fanlights, grouped double-hung windows w/ fanlight on northeast end, attached annex constructed in 1990 mimicking library to northeast.
63	Main St	103.1-2-43	C.M. Woolsey Building	1896	Commercial	3-story, 8-bay brick masonry commercial building, flat roof of unknown synthetic material, brick wall construction, stone foundation, brick piers delineate store fronts each w/ own recessed entrance & flanked by large plate glass windows, double-hung windows, 3 distinct storefronts delineated by brick piers, double-hung windows on upper stories, half-round brick lintels & oval window cartouches, brick quoining, stylized fire escape on front facade, stone name & date plaques.
	Maple Ave	103.3-2-15.300	J. Ball Foundry (1875)	1844	n/a	Concrete & stone remains of the J. Ball Foundry including upper retention pond.
1	Maple Ave	103.3-2-14	J. Ball Foundry (1875)	ca. 1850	industrial	BUILDING: 1-story wood frame single-family dwelling, metal side-gable roof w/ rear shed dormer, wood clapboard siding, stucco sided stone foundation, center entrance on enclosed porch w/ casement windows on front facade, double-hung windows w/ transoms, side entrance on west facade, double-hung windows in upper gable ends. GARAGE: 1-story wood frame garage, asphalt shingle gable roof, wood clapboard siding, sectional garage bat door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
5	Maple Ave	103.3-2-13.300	J. Ball House (1875)	ca. 1875	Italianate	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ center lower round arched cross-gable bay on front & interior brick chimney, vinyl clapboard siding, fishscale pattern wood shingle on upper gable ends, stone foundation, side entrance off of later deck on front facade, 2-story tripartite bay window on east facade, lower story tripartite bay window on front facade, single & paired double-hung windows, eave brackets.
25	Maple Ave	103.3-2-12.110	J. Ball Foundry site	ca. 1850	industrial	
	Maple Ave	103.3-2-11	Friends Burial Ground	1830	n/a	Society of Friends cemetery established in 1830, 100+ markers, stone walls delineating the cemetery, former Friends Church between Maple Avenue & cemetery razed sometime after 1875.
40	Maple Ave	103.1-3-35.200	Friends Seminary	ca. 1850	Greek Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney, vinyl clapboard siding, brick & stone foundation, side hall double door entrance, double-hung windows, walk-in basement entrance on east side, secondary entrance toward rear on west side.
53	Maple Ave	103.3-2-9.130		ca. 1890	Queen Anne	2-story wood frame single-family dwelling, slate shingle hip-gable roof w/ lower cross-gables & exterior concrete chimney on east, upper story sided in wood shingle w/ middle band of fishscale pattern shingles, lower story sided in wood clapboard, stucco sided foundation, 2 entrances off of veranda w/ turned columns & balustrades, tripartite balustrade on front façade, upper story balcony w/ square columns & balustrades over lower story tripartite bay on west façade, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
4	McLaughlin Dr	109.1-1-5	J.F. Lawson (1858)	ca. 1858	Gothic Revival	<p>HOUSE 1: 2-story, 4-bay wood frame single-family house, metal shingle cross-gable roof w/ center gable wall dormer, interior brick chimney on north end & exterior brick chimney on south end, vinyl clapboard siding, stone foundation, off center entrance off of later porch w/ concrete block balustrades, fluted columns on brick piers, double-hung windows, pointed arch double-hung windows in upper gable ends, secondary entrance toward rear on south side off of porch w/ iron railing, 1-story banked addition w/ asphalt shingle gable roof on north side,</p> <p>HOUSE 2: 1.5 story, 3-bay wood frame single dwelling, metal shingle side-gable roof, asbestos shingle siding, stone foundation, side hall entrance, small multi-pane windows & double-hung windows in upper gable ends, 1-story attached concrete block garage.</p>
	Mill House Rd	108.4-5-20.300	Mill House Orchard	ca. 1875		
66	Mill House Rd	108.4-5-20.110	John Hannigan (1891)	ca. 1891	Gothic Revival	<p>2.5 story, 2-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, wood shingle siding on lower story & wood novelty siding on upper story-and-a-half, offset entrance on east side, double-hung windows, small casement windows.</p>
6	Milton Tpke	103.1-2-46		1850	Classical Revival	<p>HOUSE: 2-story, 5-bay wood frame single-family dwelling, metal side-gable roof w/ exterior brick chimney on north end, vinyl clapboard siding, stone foundation, center hall entrance off of 3-bay wide porch w/ turned columns & balustrades, double-hung windows, later 1-story wings w/ low-pitched roof, paired double-hung windows on north wing & tripartite oriel window on south wing.</p> <p>BARN: 2-story wood frame barn, asphalt shingle gable roof, wood novelty siding, stone foundation, track barn doors on west end, upper story loft door on gable end, small square windows & secondary entrance on south side.</p> <p>MACHINE SHED: 1-story, 3-bay wood frame machine shed, asphalt shingle side-gable roof, vertical wood siding, three bay openings on east side.</p> <p>ORCHARD</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
8	Milton Tpke	103.1-2-84	Miss Soper (1875)	ca. 1800	Federal	1-story, 3-bay banked wood frame single-family dwelling, metal side-gable roof w/ interior brick chimney on east end, wood clapboard siding, stone foundation, side hall entrance w/ double-hung sidelight window off of porch w/ turned columns & later balustrades, double-hung windows, 1-story wing on west side w/ interior brick chimney on west end, basement entrance and double-hung windows under recently added porch w/ metal roof.
10	Milton Tpke	103.1-2-47	J. Caverly (1875)	ca. 1860	Gothic Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, slate shingle side-gable roof w/ clipped gable ends, flared eaves, gable dormers & interior brick chimney, wood board-&batten siding, stucco sided foundation, center hall entrance w/ transom off of wrap-around porch supported by brick piers w/ paired chamfered columns, flat sawn brackets, wood clapboard sided kneewalls, entrance flanked by double-hung windows off of 2-story rear cross-gable, single & narrow paired double-hung windows, pointed gable dormer windows, tripartite bay window on south end. BARN: 2-story banked wood frame barn, slate shingle front-gable roof w/ vented cupola, wood board-&batten siding, stone foundation, center double-door entrance w/ haymow door above, double-hung windows, wrap-around deck off northeast corner, attached machine shed & shed to south w/ wood novelty siding, later sectional doors on machine shed, 2 separate entrances on flat roof shed w/ casement windows on front & grouped double-hung windows on south end. SHED: 1-story wood frame smokehouse w/ asphalt shingle gable roof, board-&batten siding, stone foundation, entrance on east façade, double-hung windows. ORCHARD
22	Milton Tpke	103.1-2-83	D. Rowley (1875)	ca. 1875	Classical Revival	2-story wood frame single-family dwelling, asphalt shingle side-gable roof, composite shingle siding, stone foundation, off set entrance off of full porch w/ later piers & balustrades, scroll sawn brackets, double-hung windows, later 2-story wood frame wing on west w/ secondary entrance off of porch & double-hung windows, rear 2-story addition w/ double-hung windows & entrance on east side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
25	Milton Tpke	103.9-2-3	Mrs. Fowler (1875)	ca. 1850	Classical Revival	<p>HOUSE: 1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ shed dormer & lower rear cross-gable, vinyl clapboard siding, stone foundation, center entrance off of full porch single & paired double-hung windows, basement entrance & double-hung windows on east side, lower story wing on west side w/ double-hung windows & stone veneer.</p> <p>SHED: 1-story wood frame shed w/ asphalt shingle gable roof, wood novelty siding.</p>
26	Milton Tpke	103.1-2-48	D. Rowley (1875)	ca. 1830	Greek Revival	<p>HOUSE: 1.5-story banked wood frame single-family dwelling, asphalt shingle side-gable roof w/ upper rear cross-gable & exterior concrete block chimney on east end, wood clapboard siding & fishscale pattern wood shingle siding in upper gable ends, stucco sided stone foundation, side hall entrance w/ sidelights off of full 2-story porch w/ round columns & upper story balustrades, basement entrance, double-hung windows, eyebrow windows, secondary entrance toward rear on west side off of porch w/ turned columns, balustrades, & spindle brackets.</p> <p>BARN: 1-story wood frame barn, asphalt shingle gable roof, wood novelty siding, stone foundation.</p>
67	Milton Tpke	103.1-4-49	T. Mackey (1875)	ca. 1860	Classical Revival	<p>1.5-story, 3-bay w/ 2-bay wing to west, wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete block chimney on east end, wood clapboard siding, stone foundation, center hall entrance off of later replacement porch, double-hung windows, eyebrow windows.</p>
101	Milton Tpke	103.1-4-47.200	T. Furlong (1875)	ca. 1875	Classical Revival	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower rear cross-gable & interior brick chimney, vinyl clapboard siding & fishscale pattern in east upper gable end, stone foundation, center hall entrance off of wrap-around porch w/ turned columns & balustrades, double-hung windows, large oculus window on east upper gable end, large addition off rear on east side.</p> <p>GARAGE: 1-story, 2-bay wood frame garage w/ asphalt shingle roof & vinyl clapboard siding.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
132	Milton Tpke	103.1-1-33,200	S. Young (1875)	ca. 1830	Greek Revival	<p>HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on east end, vinyl clapboard siding, stone foundation, center hall entrance off of full porch w/ chamfered piers & balustrades, 2-story east wing w/ upper story balcony.</p> <p>BARN 1: 2-story banked wood frame barn, metal gable roof, wood clapboard siding, stone foundation, center wagon entrance on west side, vented openings in upper gable ends, haymow door on east side.</p> <p>BARN 2: 1.5-story wood frame barn, asphalt shingle gable roof, board-and-batten siding, stone foundation, center wagon entrance, haymow door flanked by boarded up openings, secondary entrance toward rear on east side.</p>
6	Mt Rose Rd	109.1-4-11	R. Coutant (1875)	ca. 1875	Greek Revival	<p>HOUSE: 2 story wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys, wood shingle siding, stone foundation, side hall entrance w/ transom off of later porch w/ turned columns & balustrades, single & grouped double-hung windows, 2-story wing on north w/ tripartite bay window & solarium on front facade, rear entrance w/ gable overhang on small 1-story addition.</p> <p>BARN: 1-story wood frame barn, asphalt shingle gable roof w/ birdhouse cupola, rail track doors, counterweight garage doors, double-hung windows & man door on south end.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
20-38	Mt Rose Rd	109.1-4-57		1937	Mediterranean	<p>HOUSE 1: 2-story stucco sided masonry single-family dwelling, red tile cross-gable roof w/ interior brick chimney, stucco sided masonry walls, stucco sided stone foundation, front façade w/ round arch entrance off of 2-story portico w/ upper balcony, enclosed porch w/ multi-pane metal windows, metal casement windows, rounded-corner 1-story addition w/ upper story deck, double-door entrance & large round arch multi-pane metal windows on south façade, rear round arch entrance off of 2-story portico w/ upper balcony accessed by exterior steel staircase, shallow square bays w/ large round arch multi-pane metal windows & casement windows on north façade, upper story balcony on northwest.</p> <p>HOUSE 2: 1-story stucco sided masonry single-family dwelling, red tile cross-gable roof w/ exterior brick chimney, stucco sided masonry walls, stucco sided foundation, entrance w/ gable overhang, single & paired double-hung windows, double-hung window on multi-arch recessed niche.</p> <p>INDOOR RIDING ARENA: 1-story, wood frame indoor riding arena, metal gable roof, wood panel siding, rail track doors, vented window openings underneath eaves.</p> <p>STABLE: 1-story stucco sided masonry stable, metal gable roof, stucco sided masonry walls, rail tracks doors w/ large round arch haymow doors above, Dutch stable doors on east façade.</p> <p>POOL HOUSE: 1-story stucco sided masonry pool house, red tile hip-gable roof, stucco sided masonry walls, round arch entrance flanked by small round arch windows on front façade, round arch windows on north, south & rear facades.</p>
133	North Rd	103.1-2-42	F. Underwood (1875)	ca. 1840	Greek Revival	2-story, 3-bay banked wood frame single-family dwelling, metal side gable roof, wood clapboard siding, stone foundation, side hall entrance, double-hung windows, 2-story side wing on south & 1-story attached shed on north w/ double barn doors.
151	North Rd	103.1-2-39	Mrs. E. Harcourt (1875)	ca. 1875	Classical Revival	2-story, 3-bay banked wood frame single-family dwelling, metal side-gable roof, wood clapboard siding, stone foundation, center hall entrance off of full porch above center basement entrance, double-hung windows, secondary entrance on rear lean-to addition on north side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
152	North Rd	103.1-2-25.100	Hallock House Mrs. M.E. Conkling (1875)	1760	Colonial	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side gable roof w/ interior brick chimney on north end, wood clapboard siding, stone foundation, side hall entrance off of partial porch w/ piers, 12-over-12 double-hung windows, 1.5 story side wing on north w/ asphalt shingle side-gable roof w/ interior brick chimney on north end, wood clapboard siding, stone foundation, center entrance w/ shed roof overhang, 9-over-6 double hung windows, small 4-pane half-story windows, 1-story hipped-gable wing on south.</p> <p>CIDERY: 1-story wood frame cidery, metal side gable roof w/ cupola, center multi-door entrance w/ transom, double-hung windows & large multi-pane windows on front facade.</p> <p>SHED: 1-story banked wood frame shed, asphalt shingle gable roof, asphalt shingle siding, stone foundation.</p> <p>ORCHARD</p>
159	North Rd	103.1-2-40	Chas Kent (1891)	1892	Queen Anne	<p>HOUSE: 2-story wood frame single-family dwelling, slate shingle hip-gable roof w/ interior brick chimneys & lower cross-gables, wood clapboard siding, brick & stone foundation, double-door entrance denoted by truss work gable w/ cutwork detail on wrap-around porch w/ turned columns, double-hung windows, tripartite bay window on front façade, upper story square bay on south façade.</p> <p>BARN: 2-story banked wood frame barn, metal gable roof, vertical clapboard siding, stone foundation, side entrance & haymow on south end, double-hung windows & rail track doors on east façade.</p> <p>ORCHARD</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
173	North Rd	103.1-2-57	O.P. Kent (1875)	1850	Italianate	<p>HOUSE: 1-story, 3-bay wood frame single-family dwelling, metal side-gable roof interior brick chimney & center gable wall dormer, wood clapboard siding, stone foundation, side hall entrance w/ sidelights & framed by pilasters & architrave off of full porch w/ square columns, scroll sawn brackets & balustrades, double-hung windows, paired eave brackets on frieze & porch, basement lean-to addition on south end w/ multi-pane windows & side entrance.</p> <p>GARAGE: 1-story, 3-bay wood frame garage, asphalt shingle side-gable roof, wood novelty siding, 3 sectional garage bay doors & side entrance.</p> <p>SHED 1: 1-story wood frame shed, gable roof, wood shingle siding, double-hung windows & small multi-pane window.</p> <p>SHED 2: 1-story wood frame shed, gable roof, wood novelty siding, entrance & double-hung window.</p> <p>ORCHARD</p>
177	North Rd	103.1-2-58	Rev. D. Van Fredeburgh (1875)	1830	Greek Revival	<p>HOUSE: 1.5-story, 5-bay banked wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end, wood clapboard siding, stone foundation, center hall entrance w/ Classical surround off of 2-story Gothic Revival style porch w/ broad arch brackets & balustrades, walk-in basement entrance, double-hung windows, eyebrow windows, enclosed side porch w/ series of double-hung windows; later 2-story, 3-bay addition on north w/ asphalt shingle front-gable roof, wood clapboard siding, elliptical oculus in upper gable end, double-hung windows, 2 garage bay sectional doors, deck on north end.</p> <p>CARRIAGE HOUSE: 1-story wood frame carriage house, asphalt shingle side-gable roof w/ haymow dormer, board-&batten siding, rail track doors.</p> <p>BARN: 2-story wood frame barn, metal gable roof, board-&batten siding, stone foundation, double-door entrance & haymow door on east end.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
178	North Rd	103.1-2-24	C. Kent (1875)	ca. 1875	Gothic Revival	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, metal cross-gable roof w/ exterior concrete block chimney on rear, vinyl clapboard siding, stone foundation, side hall entrance w/ shed overhang supported by truss work brackets, double-hung windows.</p> <p>BARN: 1-story wood frame barn, metal gable roof, board-and-batten siding.</p> <p>SHED: 1-story wood frame shed, asphalt shingle roof, sided w/ plywood.</p> <p>ORCHARD</p>
199	North Rd	103.1-2-67	orchard	ca. 1875		
	North Rd	103.1-2-59	orchard	ca. 1875		
204	North Rd	103.1-2-14	C.E. Stott (1875)	1859	Classical Revival	1-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable dormers & exterior brick chimney on south end, wood clapboard siding, stone foundation, roof extends over full porch w/ round columns, center hall entrance w/ double-hung windows on front facade, square bay window w/ eave brackets on south facade, later 2-story rear ell w/ hip-gable roof & exterior brick chimney on east end, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
220	North Rd	103.1-2-13	Anning Smith Homestead/A. Smith's Estate (1875)	1764	Colonial	<p>HOUSE: 2-story wood frame single dwelling now a resort, asphalt shingle side-gable roof w/ interior stone chimney & large gable wall dormer, wood clapboard siding, stone foundation, double hung windows & main entrance w/ transom framed by pilasters & architrave off of 3-bay wide porch w/ round columns on front façade, later 2-story addition to south w/ full veranda & upper deck w/ double-door entrances & small multi-pane windows, side portico w/ double-hung windows on north end, gable wall dormers w/ fanlights over double-door entrances & paired double-hung windows on rear façade.</p> <p>RESTAURANT: 2-story brick masonry & wood frame former carriage house, metal & wood shingle gable roofs, wood shingle siding & brick wall construction, double-door entrance off of portico w/ shed roof supported by cedar pier posts, 3 garage bay doors, small multi-pane windows & casement windows.</p> <p>SPA: 1-story metal & stone masonry building, flat & shed roof of unknown synthetic material, stone wall construction, concrete foundation, entrance under flat roof portico, large plate-glass windows, large metal conical oculus on roof.</p> <p>COTTAGE: 2-story banked brick masonry & wood frame cottage, metal Mansard roof w/ exterior brick chimney, wood clapboard siding & brick wall construction, stone foundation w/ 2 walk-in entrances on south, grouped double-hung windows, upper deck w/ arbor.</p> <p>CEMETERY: Small cemetery delineated by stone wall, +30 burials, unrelated statuary.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
221	North Rd	103.1-2-69	L.H. Smith (1875)	ca. 1860	Italianate	<p>HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney, asbestos shingle siding, stone foundation, entrance off of later enclosed porch under later upper story addition, double-hung windows, tripartite bay window on east side w/ paired double-hung window above, frieze band w/ paired scroll sawn eave brackets.</p> <p>CARRIAGE BARN: 1.5 story wood frame carriage barn, asphalt shingle hipped-gable roof, wood clapboard siding, series of double doors on north side, double-hung windows in upper gable end, side entrance w/ transom, paired multi-pane windows on east side.</p> <p>CONVERTED BARN: 2-story banked wood frame converted barn, asphalt shingle gable roof, wood clapboard siding, upper story double-hung windows, small lower story sliding windows, two garage bay doors on east side, side entrance toward rear on north side.</p>
238-244	North Rd	103.1-2-12.100	Buttermilk Falls industrial site	ca. 1800	industrial	
138-244	North Rd	103.1-2-12.200	Buttermilk Falls industrial site	ca. 1800	industrial	
241	North Rd	103.1-2-70	G. King (1875)	1790	Federal	<p>HOUSE: 2-story, 5-bay wood frame single-family dwelling, metal side-gable roof w/ interior brick chimneys on opposing ends, vinyl clapboard siding, stone foundation, center hall entrance w/ sidelights off of portico porch w/ turned columns & balustrades, double-hung windows, later casement window on upper story over entrance, 1-story side wings w/ grouped double-hung windows on south & secondary entrance off of latter deck on north.</p> <p>GARAGE: 1-story masonry stone garage w/ wood frame front parapet wall, low-pitched gable roof, center garage bay entrance, double-hung windows, side door entrance toward rear on south side, door entrance to left of the garage door.</p>
280	North Rd	103.1-2-4	W.H. Gedney (1875)	ca. 1875	Greek Revival	2-story, 4-bay wood frame single-family dwelling, metal front-gable roof, wood clapboard siding, stone foundation, side hall entrance off of full porch w/ tampered square columns & scroll sawn brackets, double-hung windows, double-hung window w/ half round on upper gable end, square bay window toward rear on south facade.
1	Old Indian Rd	103.3-3-8	Capt. Sears/Elverhoj Art Colony	ca. 1875/1912		Permission has yet to be given to document.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
13	Old Indian Rd	103.3-3-5	Mrs S Hallock (1875)	ca. 1875	Second Empire	<p>HOUSE: 2-story wood frame single-family dwelling, asphalt shingle Mansard roof w/ gable Mansard dormers & exterior stucco sided brick chimney, vinyl clapboard siding, brick & stone foundation, later enclosed full facade porch on east facade, rear entrance off of patio w/ later basement garage underneath, double-hung windows.</p> <p>GARAGE: 1-story, 1-bay wood frame garage w/ sectional doors, asphalt shingle gable roof, wood panel siding, sectional garage bay door, man door & double-hung window on west facade.</p>
24	Old Indian Rd	103.3-2-66.100	Elijah Lewis House	1760	Colonial	<p>HOUSE: 1-story wood frame two-family dwelling, original dwelling has asphalt shingle side-gable roof w/ interior brick chimney & lower side-gable wing w/ interior brick chimney on west end, later 1-story cross-gable addition on east, vinyl clapboard siding, stone foundation under original dwelling & concrete block foundation under later eastern addition, shed roof dormer on addition, stucco stone wall on west facade, rear lean-to addition on north, entrances w/ single & paired double-hung windows on south facade, entrance w/ sidelights & fanlight under overhang on later addition, picture window & double-hung windows on east facade.</p> <p>WELL HOUSE: Wood frame well house w/ asphalt shingle gable roof wood clapboard & lattice siding.</p>
	Old Indian Rd	103.3-2-66.100	George Inness Art Studio	1880		2-story wood frame barn & former art studio of George Inness, metal side gable roof, pattern composite shingle siding on upper story, asphalt shingle siding on lower story, stone foundation, rail track barn door, double-hung windows, shed-roof side wing w/ double doors.
304-306	Old Post Rd	108.4-4-13.100		1893	Gothic Revival	<p>HOUSE: 2-story wood frame single-family dwelling, slate shingle cross-gable roof w/ interior brick chimney, vinyl novelty siding, wood shingle siding on upper gable ends, double-door entrance off of veranda w/ turned columns, 2-story tripartite bay window, single & paired double-hung windows, later 1-story wing on south w/ concrete foundation.</p> <p>GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, vinyl novelty siding, 2 sectional garage bay doors.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
305	Old Post Rd	108.4-5-14	C. Vetic (1875)	ca. 1875	Gothic Revival	2-story, 3-bay wide wood frame two-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys & center gable wall dormers on front & rear, vinyl clapboard siding, stone foundation, double-door center hall entrance w/ transom off of 3-bay wide porch w/ turned columns & balustrades, 2-story tripartite bay window, single & paired double-hung windows, 2-story wing on south w/ side porch & double hung-windows.
330	Old Post Rd	108.4-4-16	G.W. Purdy (1875)	ca. 1875	Classical Revival	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimneys on opposing ends, vinyl clapboard siding, stucco sided stone foundation, center hall entrance w/ sidelights, double-hung windows, 2-story rear ell, paired eave brackets. SHED: 1-story wood frame shed w/ asphalt shingle gable roof & wood panel siding.
332-338	Old Post Rd	108.4-4-17.100	G.W. Purdy (1875)	ca. 1875	Classical Revival	HOUSE: 2-story, 5-bay wood frame multi-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimneys on opposing ends, vinyl clapboard siding, stucco sided stone foundation, center hall entrance w/ sidelights off of later gable roof portico, double-hung windows, paired eave brackets, 2-story rear ell w/ 1-story rear lean-to. SHED: 1-story wood frame shed, asphalt shingle gable roof, vertical wood panel siding.
341	Old Post Rd	108.4-5-12		1914	Queen Anne	HOUSE: 2 story single-family dwelling, asphalt shingle clipped cross-gable roof w/ exterior brick chimney on north end, wood clapboard siding, fishscale pattern wood shingle siding on upper gable ends, brick & stone foundation, side hall entrance off of veranda, side entrance off of west end of veranda, double-hung windows, tripartite bay window on south facade. GARAGE: 1-story, 3-bay wood frame garage, asphalt shingle side-gable roof, wood clapboard siding, 2-sectional garage bay doors & man door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
350	Old Post Rd	108.4-4-23	T. Buckley (1875)	ca. 1875	no style	<p>HOUSE: 2-story, 2-bay wood frame single-family dwelling, metal side-gable roof w/ exterior brick chimney, asbestos shingle siding, stone foundation, double-hung windows, upper story addition w/ balcony on north side w/ sliding doors & casement windows, later square oriel windows on lower & upper stories, enclosed full porch on front facade, house has been heavily altered.</p> <p>SHED: 1-story wood frame shed, asphalt shingle gable roof, wood novelty siding.</p>
351-357	Old Post Rd	108.4-5-11	E. Birdsall (1875) Shady Brook Farm	1850	Classical Revival	<p>HOUSE 1: Original house 2 is -story, 2-bay wood frame single-family dwelling, asphalt shingle side-gable w/ interior brick chimneys on opposing ends, wood clapboard siding, brick & stone foundation, center hall entrance w/ sidelights & transom off of Gothic Revival style porch w/ lattice piers & balustrades, double-hung windows, small pointed arch windows on upper gable ends, eave returns, secondary entrance w/ double-hung windows on north, 1-story wing on south sided w/ large multi-pane windows; early 20th c. 2-story, 3-bay wood frame ell, asphalt shingle roof w/ interior brick chimney & large shed wall dormers, wood clapboard siding, entrance off of hip-gable portico, on north facade, single & paired double-hung windows.</p> <p>HOUSE 2: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, wood novelty siding, stone foundation, side hall entrance off of gable portico on front facade, center entrance w/ overhang on north facade, rear entrance off of gable portico, double-hung windows.</p> <p>HOUSE 3: 2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof, wood novelty siding, concrete block foundation, off center entrance off of gable portico, double-hung windows on east & west facades, double-hung windows on lower story.</p> <p>BARN: Small 2-story wood frame barn, asphalt shingle front-gable roof, wood novelty siding, concrete pad, off set double door entrance, haymow door, 1-story rear lean-to addition.</p> <p>GARAGE: 1-story, 2-bay banked stone masonry garage w/ flat roof & parapet wall.</p>
352-360	Old Post Rd	108.4-4-24	Buckley Factory Site	ca. 1840	industrial	

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
365	Old Post Rd	108.4-5-10.100		1890	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end, wood clapboard siding, stone foundation, center hall entrance off of full brick porch w/ chamfered piers & scroll sawn brackets, double-hung windows, 1-story wing on south side w/ rear porch under roof extension, secondary entrance on north end of rear façade.
404-406	Old Post Rd	108.4-3-9	T. Buckley Residence (1875)	1843	Italianate	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys, gable dormer & large central wall dormer, wood clapboard siding, stone foundation, center hall entrance w/ fanlight & Classical surround, double-hung windows w/ lintels, 2-story wing w/ exterior brick chimney on north side entrance w/ transom off of porch w/ round columns & balustrades, eave brackets. CARRIAGE HOUSE: 1-story, 4-bay wood frame carriage house w/ rear ell, asphalt-shingle side-gable roof w/ lower rear cross-gable, gable dormers & vented cupolas, 4 garage bay sectional doors on front facade, man doors on south facade, single & paired double-hung windows.
407-409	Old Post Rd	108.4-5-7	L.S. Carpenter (1875)	ca. 1840	Greek Revival	HOUSE 1: 2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on north end & rear lower cross-gable, composite shingle siding, brick & stone foundation, side hall entrance w/ partial sidelights & classical surround off of full porch w/ later piers & balustrades, double-hung windows, basement entrance on south side. HOUSE 2: 2-story concrete masonry & wood frame single dwelling, asphalt shingle gable roof w/ large shed dormer, upper story sided in board-and-batten, concrete lower story construction, double door entrance with shed roof overhang, paired casement windows, full porch on north end.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
411	Old Post Rd	108.4-5-33		Ca. 1850	Italianate	HOUSE: 2-story, 3-bay wide wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, wood clapboard siding, stucco sided stone foundation, side hall entrance off of full porch w/ turned columns, scroll sawn brackets, scroll sawn balustrades, double-hung windows w/ lintels & sills, eave brackets, decorative cornice appliques, basement entrance w/ shed roof overhang on south side. SHED: 1-story brick masonry shed, center entrance flanked by casement windows, secondary entrance on north side.
417	Old Post Rd	108.4-5-5	T. Buckley (1875)	ca. 1830	Greek Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete block chimney on south end, vinyl clapboard siding, stucco sided stone foundation, side hall entrance w/ sidelights & transom off of full porch w/ later piers & balustrades, later picture window to left of entrance, double-hung windows, rear lower story additions.
420	Old Post Rd	108.4-3-13		1926	Colonial Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior and exterior brick chimneys, wood clapboard siding, brick & stone foundation, side hall entrance w/ sidelights & fanlight off of gable roof portico w/ eave returns & turned columns, double-hung windows, full porch on south side w/ clapboarded knee wall & turned columns, 1-story wing w/ casement windows on north side. BARN: 2-story wood frame barn, asphalt shingle gable, roof, wood novelty siding, stone foundation, track rail doors on west & south sides, loft door upper gable end, shed addition on south side.
422	Old Post Rd	108.4-3-14		1928	Craftsman/Bungalow	1-story wood frame single-family dwelling, asphalt shingle clipped-gable roof w/ clipped-gable dormers & interior brick chimney, wood clapboard siding, concrete foundation, entrance on south side w/ gable overhang & brackets, single & paired double-hung windows, 1-story wing on north side w/ secondary entrance, eave brackets.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
424	Old Post Rd	108.4-3-15		1900	Colonial Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stucco sided stone foundation, center hall entrance w/ sidelights off of portico w/ chamfered piers & balustrades, lower story grouped double-hung windows, upper story single double-hung windows, attached 1-bay garage w/ flat roof on north side, 1-story wing w/ grouped double-hung windows on south side.
426	Old Post Rd	108.4-3-16	Christ Episcopal Church	1858	Gothic Revival	CHURCH: Brick masonry church, high-pitched slate shingle roof w/ rear interior brick chimney, brick wall construction, stone foundation, entrance at base of 3-story belfry tower, tripartite rear apse w/ pointed arch stained windows, wall buttresses, large pointed arch stained glass windows on north & south facades, paired pointed arch stained glass windows w/ quadfoil window on front façade. CEMETERY: Church cemetery w/ +200 burials including family plot delineated by cast iron fence, earliest burials in 1840s.
428-430	Old Post Rd	108.4-3-17	T. Buckley (1875)	1863	Gothic Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ large center gable wall dormers & interior brick chimney, vinyl clapboard siding, stone foundation, center hall entrance w/ partial sidelight, double-hung windows, 2 tripartite bay windows on south façade, 1-story wing on north. MEMORIAL: Sandstone memorial dedicated to Reverend Samuel Hawksley, Rector of Christ Church Marlborough.
20-22	Orange St	108.12-1-24		1900	no style	2-story wood frame single dwelling, asphalt shingle hipped-gable roof, vinyl clapboard siding, side entrance on front facade, secondary entrance on south side, single, paired, & grouped double-hung windows, 1-story, 2-bay wood frame attached garage.
34	Orange St	108.12-7-5		1890	Classical Revival	2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end, vinyl clapboard siding, stucco sided stone foundation, center hall entrance off of later partial porch w/ upper balcony, double-hung windows, secondary entrance off of porch toward rear on south side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
36	Orange St	108.12-7-8		ca. 1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt-shingle side gable roof w/ interior brick chimney, composite shingle siding, stucco sided stone foundation, side hall entrance off of full porch, double-hung windows, tripartite oriel window on south facade, upper story addition on front facade over porch.
38	Orange St	108.12-7-9		1920	Craftsman Cottage	HOUSE: 1-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ gable wall dormers on north & south facades & exterior brick chimney on south side, vinyl clapboard siding, concrete foundation, center entrance flanked by casement windows on front facade, double-hung windows on south facade & sliding eyebrow windows on north facade. GARAGE: 1-story, 2-bay masonry garage, asphalt shingle side-gable roof, stucco sided concrete walls, sectional garage bay doors.
39	Orange St	108.12-4-3		1954	Ranch	2-story concrete masonry & wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on south end, vinyl clapboard siding on upper story & concrete block wall construction on lower story, concrete pad, 2 garage bay sectional doors, double-hung & sliding glass windows on front facade, double-hung windows on north & south facades.
40	Orange St	108.12-7-10		1924	Craftsman Cottage	1-story, 3-bay wood frame single family dwelling, asphalt shingle front-gable roof w/ exterior brick chimney on south & gable walls dormers toward rear on north & south facades, vinyl clapboard siding, brick & concrete foundation, center entrance flanked by sliding glass windows, sliding glass windows on north & south facades, enclosed rear porch.
44	Orange St	108.12-7-11		1904	Queen Anne	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior concrete block chimney, vinyl clapboard siding, stucco sided stone foundation, side hall entrance off of wrap-around porch w/ turned columns, decorative spandrels, balustrades, corner porch gable w/ decorative stickwork, decorative gable truss work, single & paired double-hung windows. GARAGE: 1-story, 2-bay brick masonry garage, asphalt shingle gable roof, vinyl clapboard siding in upper gable end.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
45	Orange St	108.12-4-4		2006	no style	2-story wood frame two-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, 2 separate entrances w/ tripartite oriel windows & double-hung windows on front facade, secondary entrance on north facade, rear basement garages w/ sectional doors.
48	Orange St	108.12-7-14		1925	Foursquare	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ exterior brick chimney & hip dormer, vinyl novelty siding, concrete foundation, 1-story, 1-bay wings on north & south sides, center entrance on full enclosed porch w/ grouped double-hung windows, single double-hung windows. GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle hip-gable roof, vinyl novelty siding, sectional garage bay door.
50	Orange St	108.12-7-15		ca. 1871	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, asbestos shingle siding over wood clapboard siding, stone foundation, side hall entrance off of later wrap-around porch w/ corner step approach & brick piers, double-hung windows, 1-story rear addition w/ paired double-hung windows off of southwest corner.
51	Orange St	108.12-4-32		ca. 1891	no style	2-story, 2-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, entrance on front façade off of veranda, double-hung windows, lower rear cross-gable addition w/ casement windows & 2 sectional garage bay doors on north façade.
54	Orange St	108.12-7-18		1950	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on south end, vinyl novelty siding, concrete foundation, center entrance off of gable portico, double-hung windows, basement garage w/ sectional door.
55	Orange St	108.12-4-31		ca. 1891	no style	1-story, 2-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, wood shingle siding, stone & concrete foundations, side hall entrance off of full porch, single & paired double-hung windows, 1-story wood frame addition on south w/ paired casement windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
56	Orange St	108.12-7-19.200		1954	Cape Cod	1-story, 3-bay brick masonry single-family dwelling, asphalt shingle side-gable roof w/ gable dormers, brick wall construction w/ vinyl clapboard siding in upper gable ends, concrete block foundation, off center entrance w/ double-hung window & tripartite oriel window on front facade, basement garage w/ sectional door.
57	Orange St	108.12-4-28	Mrs. Valentine (1875)	ca. 1875	Gothic Revival	HOUSE: 2-story, 4-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ high-pitched center gable wall dormer & interior brick chimney, vinyl clapboard siding, stone foundation, two later side hall entrances on opposing ends of front facade w/ later shed roof porticos, double-hung windows, narrow paired double-hung windows in gable dormer, small 1-story attached garage on north side, paired eave brackets. SHED: 1-story wood frame shed w/ asphalt shingle shed roof & vinyl clapboard siding.
58	Orange St	108.12-7-21		ca. 1891	Queen Ane	1-story, 3-bay wood frame multi-family dwelling, asphalt shingle front-gable roof w/ large gable wall dormers on north & south, vinyl novelty siding, stucco sided stone foundation, center hall entrance off of veranda, double-hung windows, large 1-story concrete & brick masonry rear addition.
59	Orange St	108.12-5-27		1910	no style	HOUSE: 1-story 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete chimney, vinyl clapboard siding, concrete foundation, entrance off of gable portico, casement windows. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle front-gable roof, vinyl clapboard siding, sectional garage bay door, man door.
60	Orange St	108.12-7-22		1950	Craftsman Bungalow	HOUSE: 1-story, 3-bay wood frame ,single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on north end & large shed dormer, vinyl clapboard siding, concrete foundation, roof extends over porch w/ center entrance & double-hung windows, small wing on south, later upper entrance off of stairs on north end. GARAGE: 1-story, 1-bay concrete block garage, gable roof w/ small multi-pane window in upper gable end, garage bay door replaced w/ man door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
62	Orange St	108.12-7-25		1930	no style	2-story, 3-bay wood frame two-family dwelling, low-pitched asphalt shingle side-gable roof w/ interior concrete chimney, vinyl clapboard siding, concrete foundation, center double-door basement entrance with partial sidelights, sliding door entrance off of 2-story deck on front facade, double-hung windows, rear upper story entrance on southwest corner off of upper deck.
69	Orange St	108.12-4-22		1957	Ranch	1-story wood frame single-family dwelling, low-pitched asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, exterior vestibule side entrance, paired & grouped double-hung windows on front facade, casement windows on south facade, single double-hung windows & basement garage on north facade, rear enclosed porch.
70	Orange St	108.12-6-3		1948	Ranch	1-story, 4-bay wood frame single-family dwelling, low-pitched side-gable roof, vinyl clapboard siding, concrete foundation, entrance off of recessed corner porch, double-hung windows, basement garage w/ sectional door.
71	Orange St	108.12-5-1		1950	Ranch	1-story, brick masonry single-family dwelling, asphalt shingle hip-gable roof, brick wall construction, concrete foundation, entrance on front & south facades, double-hung windows, casement windows, large plate glass corner windows on southwest.
72	Orange St	108.12-6-4		1956	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle cross hip-gable roof, aluminum clapboard siding, concrete foundation, entrance & double-hung window on projecting hip-gable ell, oriel window over basement garage w/ sectional door, double-hung windows on south & north facades.
73	Orange St	108.12-6-6		1955	Ranch	1-story brick masonry single-family dwelling, asphalt shingle hip-gable roof w/ interior brick chimney, brick wall construction w/ wood shingle siding on rear, concrete foundation, recessed entrance & double-hung windows on front facade, secondary entrance & double-hung window on north facade.
74	Orange St	108.12-6-6		1955	Ranch	1-story wood frame single-family dwelling, low-pitched asphalt shingle side-gable roof w/ exterior brick chimney on south end, vinyl clapboard siding, concrete foundation, entrance on south side of projecting bay, tripartite oriel window on front facade, tall paired casement windows above basement garage & on north & south facades, sectional garage bay door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
79	Orange St	108.12-5-24	S. Penny (1875)	ca. 1870	Gothic Revival	2-story, 5-bay banked wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end & center gable wall dormer, aluminum clapboard siding, brick foundation, center hall entrance w/ transom off of partial porch w/ brick piers & knee walls, double-hung windows, later paired double-hung windows & casement windows, round arch double-hung dormer window, later 2-story wing addition on south side w/ paired double-hung windows & enclosed brick & wood frame side entrance.
80	Orange St	108.12-6-7.100		2001	Cape Cod	1-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior vinyl clapboard chimney & gable dormers, vinyl clapboard siding, concrete foundation, roof extends over porch w/ center hall entrance w/ partial sidelights, double-hung windows, double-hung windows w/ half round transoms on dormers, 2-story attached garage on north end w/ asphalt shingle side gable roof, gable wall dormer, shallow double-door balcony flanked by paired double-hung windows, large multi-pane dormer window, sectional garage bay door, secondary double-door entrance onto upper story deck on north end.
84	Orange St	108.12-6-8		1958	Ranch	1-story wood frame single-family dwelling, asphalt shingle side-gable roof, composite clapboard siding & vinyl clapboard siding on upper gable ends, concrete foundation, side entrance off of concrete deck w/ iron balustrades, picture window & paired double-hung windows on front facade, basement garage w/ sectional door.
86	Orange St	108.12-6-11		1955	Cape Cod	1-story wood frame single-family dwelling, low-pitched asphalt shingle gable roof w/ exterior brick chimney, composite clapboard siding, concrete block foundation, center entrance off of recessed porch, single & paired double-hung windows, walk-in basement entrance garage w/ sectional door.
88	Orange St	108.12-6-12		1955	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower projecting hip-gable w/ exterior brick chimney on north end, aluminum clapboard siding, brick & concrete foundation, entrance off of recessed corner, double-hung windows, tripartite oriel window on front facade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
90	Orange St	108.12-6-13		1985	Cape Cod	1-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney & gable dormers, vinyl clapboard siding, concrete foundation, recessed center hall entrance w/ partial sidelights, double-hung windows
91	Orange St	108.12-5-20		1960	Ranch	1-story wood frame single-family dwelling, low-pitched asphalt shingle side-gable roof w/ interior brick chimney on south end, vinyl clapboard siding w/ brick veneer on lower half of front facade, concrete foundation, side entrance off of open veranda, paired & grouped double-hung windows on front facade, secondary entrance on south end, double-hung windows on north & south facades.
92	Orange St	108.12-6-16		1955	Cape Cod	1-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable dormers & exterior brick chimney, vinyl clapboard siding, concrete foundation, center hall entrance w/ partial sidelights, double-hung windows.
93	Orange St	108.12-5-19		1930	no style	1-story, 6-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ exterior brick chimney on south side, vinyl clapboard siding, concrete foundation, 2 entrances flanked by double-hung windows off of full porch w/ hip-gable roof, later rear deck, basement entrance & double-hung windows on north facade.
94	Orange St	108.12-6-17		1953	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower cross-gable & exterior brick chimney on south end, wood shingle siding & vinyl clapboard siding on upper gable ends, concrete foundation, center entrance off of gable portico, double-hung windows, picture windows over basement garage w/ sectional door.
96	Orange St	108.12-6-18		1954	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle cross hip-gable roof, vinyl clapboard siding, concrete foundation entrance off of hip-gable portico, double-hung windows, oriel window, basement garage w/ sectional door.
1	Orchard St	108.12-1-25		ca. 1880	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance off of later full porch w/ piers & balustrades, double-hung windows, later 1-story wing w/ paired double-hung windows on south side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
2	Orchard St	108.12-1-34		ca. 1880	Classical Revival	2.5-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on south end, vinyl clapboard siding, stucco sided stone foundation, side hall entrance off of later open porch, double-hung windows, eyebrow windows.
3	Orchard St	108.12-1-26		ca. 1880	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, side hall entrance off of later open full porch w/ lattice piers, double-hung windows.
4	Orchard St	108.12-1-33		ca. 1880	Gothic Revival	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney on south end & gable wall dormer, vinyl clapboard siding, stone foundation, off set entrance off of wrap-around porch w/ later piers & balustrades, single & paired double-hung windows, large picture window, paired casement windows, secondary entrance off of porch toward rear on south side, narrow single pane windows in upper gable ends. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof w/ large shed wall dormer, aluminum clapboard siding, 2-bay door entrances.
5	Orchard St	108.12-1-27		ca. 1880	no style	2-story wood frame two-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, aluminum clapboard siding, lower story brick construction, side hall entrance off of later partial porch w/ wood columns on brick piers & iron balustrades, exterior altered w/ original windows removed, single & grouped casement windows added.
6	Orchard St	108.12-1-32		1950	Ranch	HOUSE: 1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof, composite shingle siding w/ composite clapboard siding on upper gable ends., concrete foundation, side entrance w/ picture & paired double-hung windows on front facade, single double-hung windows on north & south facades. GARAGE: 1-story, 2-bay concrete block masonry garage, asphalt shingle gable roof, concrete block construction w/ composite clapboard siding on upper gable end, sectional garage bay doors, 1-story lean-to addition w/ double-doors & vinyl clapboard siding.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
7	Orchard St	108.12-1-28		ca. 1880	Classical Revival	2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ low-pitched 2-story wing on south side, exterior brick chimney on south end, vinyl clapboard siding, stone foundation, side hall entrance off of later partial porch w/ decorative iron piers & paired double-hung window, single double-hung windows.
17	Orchard St	108.12-7-6		ca. 18880	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney & lower cross-gable, vinyl clapboard siding, stone foundation, entrance flanked by double-hung windows on south end of enclosed porch w/ paired encasement windows, double-hung windows.
20	Orchard St	108.12-7-39		1920	Craftsman Cottage	HOUSE: 1-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ lower cross-gables & exterior brick chimneys, vinyl novelty siding, stucco sided foundation, center entrance w/ sidelights & transom on full enclosed porch w/ brick piers & round columns, double-hung windows, eave brackets. GARAGE: 1-story wood frame garage, asphalt shingle gable roof, vinyl novelty siding, sectional garage bay door & side entrance.
21	Orchard St	108.12-7-7		1928	Craftsman Cottage	1-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ hip dormer & exterior cobble chimney, wood shingle siding, concrete foundation w/ cobblestone surface, roof extends over over porch w/ later iron piers & balustrades, off center entrance w/ single & grouped double-hung windows, square bay window on south facade, enclosed rear porch, exposed rafter ends, basement garage w/ sectional door toward rear on north facade
24	Orchard St	108.12-7-42		ca. 1900	no style	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof, vinyl clapboard siding, stone foundation, side-hall entrance off of full porch w/ later square columns & iron balustrades, picture window & grouped double-hung windows on front façade, paired double-hung windows on south façade, single double hung windows on north façade, 1-story rear addition. GARAGE: 1-story, 1-bay wood frame garage w/ asphalt shingle gable roof, wood novelty siding, sectional garage bay door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
25	Orchard St	108.12-7-12		ca. 1880	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney & shed roof on rear, vinyl clapboard siding, brick & concrete foundation, later exterior vestibule over original side hall entrance, double-hung windows, square bay w/ casement windows on south facade, later rear deck.
29	Orchard St	108.12-7-13		1940	Craftsman Cottage	1-story, 3-bay wood frame single-family dwelling, asphalt shingle hip-gable roof extending over enclosed porch, composite clapboard siding, concrete foundation, center entrance flanked by double-hung windows off of full enclosed porch, picture & double-hung windows on north facade, double-hung windows on south facade, basement garage w/ sectional door toward rear on north facade.
31	Orchard St	108.12-7-16		1961	Ranch	1-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ interior brick chimney, aluminum clapboard siding, concrete foundation, center entrance w/ picture & double-hung windows on front facade, double-hung windows on north & south facades.
33	Orchard St	108.12-7-17		1930	Craftsman Cottage	HOUSE: 1-story, 3-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ interior brick chimney, vinyl clapboard siding, stucco sided foundation, roof extends over full porch w/ center entrance flanked by double-hung windows, double hung windows on north & south facades, wall-in basement entrance & garage on rear facade. SHED: 1-story wood frame shed w/ asphalt shingle gable roof & novelty siding.
37	Orchard St	108.12-7-19.100		1925	Craftsman Cottage	1-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ hip-gable dormer & interior brick chimney, vinyl clapboard siding, concrete foundation, center entrance off of full enclosed porch w/ paired casement windows, single & paired double-hung windows on north & south facades, walk-in basement entrance & garage w/ 2 sectional doors toward rear on south facade.
40	Orchard St	108.12-7-32.150		1930	Craftsman Cottage	1-story wood frame single-family banked dwelling, asphalt shingle hip-gable roof w/ exterior brick chimney, vinyl clapboard siding, stucco sided stone foundation, roof extends over full porch w/ off center porch & double-hung windows, enclosed rear porch, double-hung windows on north & south facades, walk-in basement entrance.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
41	Orchard St	108.12-7-20		1960	Ranch	1-story brick masonry single-family dwelling, asphalt shingle hip-gable roof w/ lower cross-gable & interior brick chimney, brick wall construction, concrete block foundation, angled entrance surrounded by stone veneer on recessed corner porch, double-hung windows on north & south facades, casement window on front facade, rear wrap-around deck.
45	Orchard St	108.12-7-23		1940	Bungalow/Craftsman	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side gable roof w/ gable dormer & exterior concrete chimney on south end, wood shingle siding, stucco sided foundation, roof extends over front porch w/ later iron piers & balustrades, center entrance flanked by double-hung windows, double-hung windows on north & south facades, enclosed rear porch.
47	Orchard St	108.12-7-24		1955	Cape Cod	1-story, 3-bay brick masonry single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end, brick wall construction & vinyl clapboard siding on upper gable ends, concrete block foundation, center entrance w/ single & paired double-hung windows on front facade, double-hung windows on north & south facades, summer porch on south end.
49	Orchard St	108.12-7-26		1940	Ranch	1-story brick masonry single family dwelling, low-pitched asphalt shingle cross-gable roof w/ interior brick chimney & exterior concrete chimney on south end, brick wall construction & vinyl clapboard siding in upper gable ends, concrete block foundation, center entrance w/ picture & double-hung windows on front facade, double-hung windows on north & south facades, small 1-story wood frame side wing on south.
51	Orchard St	108.12-7-27		1956	Ranch	1-story, 3-bay brick masonry single-family dwelling, low-pitched asphalt shingle side-gable roof w/ interior brick chimney, brick wall construction & vinyl clapboard siding on upper gable ends, concrete block foundation, center entrance w/ picture & double-hung windows on front facade, double-hung windows on north & south facades, later added rear deck.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
53	Orchard St	108.12-7-28		1940	Ranch	1-story brick masonry two-family dwelling, asphalt shingle hip-gable roof w/ lower cross gable & exterior brick chimney on north end, brick wall construction & vinyl clapboard siding, concrete block foundation, off center entrance & picture windows on front facade, 1-story wood frame addition off southwest corner w/ casement windows & cobblestone foundation, walk-in basement entrance on south end, basement garage w/ 2 sectional doors on rear.
57	Orchard St	108.12-6-2		1960	Ranch	1-story wood frame single-family dwelling, asphalt shingle cross hip-gable roof w/ interior brick chimney, vinyl novelty siding, concrete foundation, recessed entrance w/ casement & double-hung windows on front facade, walk-in basement entrance & garage w/ sectional door on north facade.
59	Orchard St	108.12-6-5		1955	Ranch	1-story wood frame & brick masonry single-family dwelling, asphalt shingle hip-gable roof w/ interior brick chimney & exterior brick chimney on north end, wood shingle siding, concrete foundation, off center recessed entrance w/ sidelights, paired double-hung windows, secondary entrance & attached garage w/ sectional door at south end of front facade, rear deck..
62	Orchard St	108.12-6-25.200		1966	Ranch	1-story, 3-bay brick masonry single-family dwelling, asphalt shingle hip-gable roof, brick wall construction, concrete foundation, double-hung windows, walk-in basement entrance & garage bay doors on south facade.
63	Orchard St	108.12-6-7.200		ca. 1880	Second Empire	2.5 story, 5-bay wood frame multi-family dwelling, asphalt shingle Mansard roof w/ brick chimney on south end & arched double-hung window dormers, vinyl clapboard siding, stone foundation, center hall entrance w/ sidelight & transom off of 3-bay wide porch w/ slender piers & scroll sawn brackets, double-hung windows, covered paired eave brackets, 2-story wing on south side w/ flat roof porch & covered eave brackets.
67	Orchard St	108.12-6-9		ca. 1891	no style	2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding & wood clapboard siding on front facade, stone foundation, off center entrance w/ gable overhang, double-hung windows, side entrance toward rear on south facade, basement garage w/ sectional door on north facade, 1-story rear addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
71	Orchard St	108.12-6-10		1955	Cape Cod	1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, concrete foundation, entrance off of gable portico, oriel window, double-hung windows, oriel window on south facade, attached garage w/ sectional garage bay door.
74	Orchard St	108.12-6-23.100		2005	Colonial	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable wall dormer & exterior chimney sided in vinyl clapboards, vinyl clapboard siding, concrete foundation, center hall entrance w/ sidelights off of partial porch, double-hung windows, basement garage w/ large sectional door.
75	Orchard St	108.12-6-14		1953	Ranch	1-story wood frame single-family dwelling, low-pitched asphalt shingle hip-gable roof w/ lower cross hip-gables, exterior brick chimney, vented cupola, wood shingle siding, concrete foundation, center entrance under hip-roof overhang, double-hung & casement windows on front facade, double-door side entrance on south wing, double-hung windows on north facade.
76	Orchard St	108.12-6-23.200		2005	Colonial	2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable wall dormer & exterior chimney sided in vinyl clapboards, vinyl clapboard siding, concrete foundation, entrance w/ sidelights off of portico, single & paired double-hung windows, tripartite oriel window, basement garage w/ large sectional door.
78	Orchard St	108.12-6-22		1956	Ranch	1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower cross-gable & interior brick chimney, wood shingle siding, concrete foundation, sliding door entrance off of deck, double-hung windows, basement garage w/ sectional door.
81	Orchard St	108.12-6-15.200		1989	no style	1-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ exterior chimney sided in wood clapboard, wood clapboard siding, concrete foundation, entrance toward rear on south facade off of wrap-around deck, secondary entrance on north facade, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
82	Orchard St	108.12-6-20		1966	Split Level	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower side-gable & exterior concrete chimney, composite clapboard siding & fishscale pattern shingle siding in upper gable ends, concrete foundation, off center entrance off of deck, picture window, double-hung windows, basement garage w/ sectional door. SHED: 1-story, 1-bay wood frame shed w/ gable roof & wood panel siding.
86	Orchard St	108.4-6-22		1975	Ranch	1-story brick masonry single-family dwelling, asphalt shingle hip-gable roof w/ exterior brick chimney, brick wall construction, concrete foundation, center entrance flanked by picture windows on front facade, double-hung windows, paired horizontal casement windows, walk-in basement entrance & garage w/ sectional door on north end.
92-94	Orchard St	108.4-6-23		1992	Manufactured	1-story wood frame two-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, 2 separate entrances & paired double-hung windows on front facade, side entrance w/ single double-hung window & basement garage w/ sectional door on north facade.
2	Plattekill Rd	108.2-7-34.100	J. Clark (1858)	ca. 1850	Second Empire	1-story, 5-bay wood frame single-family dwelling, Mansard roof w/ brick chimneys on southwest end & rear, large projecting gambrel wall dormer & segmental arch dormers, roof & walls sided in composite clapboard, stone foundation, center hall entrance w/ partial sidelights off of 3-bay wide porch, double hung windows, 1-story wing on southwest, lower 1-story w/ Mansard roof & sectional garage bay door on northeast.
9	Plattekill Rd	108.2-6-5	H. McCourt (1875)	1860	Classical Revival	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete block chimney on east end, vinyl clapboard siding, stone foundation, center hall entrance w/ sidelights off of full porch w/ turned columns & balustrades, double-hung windows, eyebrow windows, octagonal oculus window over entrance. BARN: 1-story wood frame barn, asphalt-shingle gable roof, wood novelty siding, stone foundation, double-hung windows, lower 1-story side gable w/ entrance & siding windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
55	Plattekill Rd	108.4-2-1	A. & D. Dubois (1858)	ca. 1820	Federal	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys at opposing ends, wood clapboard siding, stone foundation, center hall double door entrance w/ transoms off of 3-bay wide porch w/ fluted columns, double-hung windows w/ lintels & sills, eave brackets, attached 2-bay garage on west side, 1-story wing w/ secondary entrance & casement windows on east. SHED: 1-story stone masonry shed, former lower story of earlier barn.
58	Plattekill Rd	108.2-7-40.100	barn	ca. 1875	no style	1-story wood frame barn, metal side gable roof w/ cupola & weathervane, wood novelty siding, stone foundation, rail track doors, 1-story attached elongated stone structure w/ shed roof & sectional garage bay door on southeast end.
66	Plattekill Rd	108.2-7-42.120	J. Toomey (1875)	ca. 1875	Classical Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance w/ partial sidelights off of wrap-around porch w/ square columns & balustrades, double-hung windows. GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof, vinyl clapboard siding. SHED: 1-story wood frame, shed roof, asphalt shingle siding, small pane & casement windows, off set entrance.
85	Plattekill Rd	108.4-1-11.200	J. Dubois (1875)	1860	Classical Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys on opposing ends, wood clapboard siding, stone foundation, center hall entrance w/ sidelights off of 3-bay wide porch w/ chamfered columns & scroll sawn brackets, double-hung windows w/ lintels & sills, 1-story rear ell w/ tripartite bay & rear porch.
6	Prospect St	108.12-2-6		1879	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance off of full porch w/ turned columns & scroll sawn brackets, double-hung windows, later side porch w/ entrance on south side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
7	Prospect St	108.2-5-18	Eckerson (1891)	1887	Queen Anne	2-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ lower cross-gables & gable wall dormers, wood shingle siding on upper gable ends & wood clapboard siding on lower stories, stone foundation, double-door entrance on east façade off of wrap-around porch w/ turned columns & balustrades, single & paired double-hung windows, 2-story square bay window on southeast corner, double-door entrance flanked by tall multi-pane windows under arbor at north end of porch.
8	Prospect St	108.12-2-4	Henessey (1891)	ca. 1891	Queen Anne	HOUSE 1: 2-story banked wood frame single-family dwelling, metal cross-gable roof w/ clipped gables & interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance on south side off of partial porch w/ turned columns, brick piers, & later balustrades, rear entrance off of summer porch on north end of 2-story wing w/ asphalt shingle gable roof, double-hung windows, square bay window toward rear on west side, original wrap-around porch enclosed on east side. HOUSE 2: 1-story wood single dwelling, low-pitched asphalt shingle gable roof, vertical wood panel siding, concrete foundation, double door entrance, double-hung windows. BARN: Small 2-story wood frame barn, asphalt shingle gable roof, wood novelty siding, stone foundation, side entrance & rail track door on south side, upper loft door.
9-11	Prospect St	108.2-5-19	Dubois (1891)	1888	Classical Revival	2-story, 3-bay wood frame single-family dwelling dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, concrete block foundation, side hall entrance off of full enclosed porch w/ double-hung windows, double-hung windows, square bay window toward front of south side, 1-story flat roof wing on north side, 2-story flat roof rear addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
13-19	Prospect St	108.2-5-20	Gillespie (1891)	1890	Queen Naae	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle clipped-gable roof w/ projecting clipped-gable dormer, asbestos shingle siding, stucco sided stone foundation, center hall double door entrance with transoms off of 3-bay wide porch, single & paired double-hung windows, square bay windows toward front on north & south sides, later added lower-story picture window on north side.</p> <p>CONVERTED BARN: 2-story wood frame barn converted into apartments, asphalt shingle front-gable roof w/ lower pitched side-gable, aluminum clapboard siding, brick foundation, later added fenestration including casement windows, double-hung windows, & picture windows, lower & upper apartment entrances on north side.</p>
62	Prospect St	108.2-5-1	Misses C. & H. Berrian (1875)	1871	Italianate	<p>HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on north end, aluminum clapboard siding, stone foundation, center hall entrance off of 3-bay wide porch w/ turned columns & spandrels, double-hung windows, 1-story wing on north side w/ paired double-hung windows, 1-story rear lean-to off southeast corner w/ secondary entrance, paired eave brackets.</p> <p>GARAGE: 1-story, 1-bay wood frame garage w/ carport, asphalt shingle cross-gable roof, wood clapboard siding.</p>
6	Quarry Rd	108.4-4-22	T. Buckley (1875) Mill-related building	ca. 1875	Industrial	<p>HOUSE: 1-story banked wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney & lower metal cross-gable roof, vinyl clapboard siding, brick & stone foundation, separate basement level entrances w/ large multi-pane windows, double-hung windows, 1-story rear lean-to w/ paired double-hung windows.</p> <p>GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, wood clapboard siding, two sectional bay doors, double-hung windows.</p>
94	Riverview Dr	109.1-2-37	Milton Train Station	1883	Transportation	1-story, wood frame railroad depot, hipped roof, wood shingle siding

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
12	Sands Ave	103.1-3-13.100	J. Handley (1875)	ca. 1875	Stick Style	HOUSE: 2-story, 2-bay wood frame single-family dwelling, asphalt shingle cross-gable roof, wood clapboard siding, belt boards between stories, wood shingles in gable, stone foundation, side hall entrance with deep gabled porch. BARN: 1.5-story wood frame, gable roof, center vehicle bay with sliding doors; 1-story addition.
17	Sands Ave	103.9-1-25	Mrs. Foreman (1875)	ca. 1875	Queen Anne	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end & large central projecting 2-story octagonal tower w/ flared hipped-roof, vinyl novelty siding, brick & stone foundation, center hall entrance w/ sidelights off of full porch, double-hung windows, 2-story porch on south side, rear 2-story wood frame addition.
23	Sands Ave	103.9-1-23	R.H. Roe (1875)	ca. 1875	Gothic Revival	2-story, 3-bay wood frame two-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney & clipped front gable, vinyl clapboard siding, stone foundation, side hall entrance off of full enclosed porch w/ paired double-hung windows, double-hung windows, full gable pediment on front.
27	Sands Ave	103.9-1-22	T. Purdy (1875)	1853	Gothic Revival	HOUSE: 1-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower front cross-gable extending over 3-bay wide porch w/ decorative fretwork, square columns, & balustrades, vinyl clapboard siding, stone foundation, interior brick chimney, shed dormer on north end, off center entrance w/ sidelights, double-hung windows w/ lintels & sills on front façade, tripartite bay window, eave pendants, vergeboards w/ rosette appliques. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle front-gable roof, fishscale pattern wood shingle in upper gable end, vinyl clapboard siding.
29	Sands Ave	103.9-1-21		1920	Craftsman Cottage	1-story, 3-bay wood frame single-family dwelling, asphalt shingle hipped-roof w/ hipped dormer, vinyl clapboard siding, concrete block foundation, center entrance off of full porch under roof w/ later square columns on brick piers & later balustrades, double-hung windows, secondary entrance toward rear on south side.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
31	Sands Ave	103.9-1-20	Rev. P.C. Oakley (1875)	ca. 1850	Greek Revival	<p>HOUSE: 1-story, 3-bay wood frame single-family dwelling, asphalt shingle gambrel roof w/ large shed dormer & interior brick chimney on south end, vinyl clapboard siding, stucco sided stone foundation, side hall entrance w/ sidelights off of full porch w/ round columns & balustrades, double-hung windows, eave returns, 1-story rear addition off northwest corner w/ double-hung windows.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle front-gable roof, aluminum clapboard siding.</p>
33	Sands Ave	103.9-1-18	C.T. Ordway (1875)	1860	Classical Revival	<p>2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end, vinyl clapboard siding, stone foundation, center hall entrance w/ sidelights off of full porch w/ round columns, balustrades, & front-gable denoting entrance, double-hung windows, 1-story rear addition w/ large bay window & attached carport on north side.</p>
38	Sands Ave	103.1-3-10	C.A. Valentine (1875)	ca. 1875	Classical Revival	<p>HOUSE: 2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end & interior masonry chimney on south end, asbestos shingle siding, stone foundation, off center entrance off of full porch w/ later posts & lattice balustrades, double-hung windows, 1-story rear addition & later porch.</p> <p>SHED: 1-story wood frame shed w/ metal roof & wood clapboard siding.</p>
42	Sands Ave	103.1-3-9	Schoolhouse foundation	ca. 1840	Gothic Revival	Fieldstone foundation of amid to late-19th century schoolhouse.
43	Sands Ave	103.9-1-14	S. Freer (1875)	ca. 1870	Classical Revival	<p>HOUSE: 1-story banked wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys on opposing ends & center gable wall dormer, vinyl clapboard siding, stone foundation, center hall entrance off of full enclosed porch w/ later encasement windows, double-hung windows, later large deck on north side.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle front-gable roof, vinyl clapboard siding.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
46	Sands Ave	103.1-3-7	J.H. Newman (1875)	ca. 1875	Gothic Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys, wood clapboard siding, brick & stone foundation, double-door center hall entrance off of Gothic Revival style portico w/ chamfered columns & flat sawn balustrades, entrance flanked by later tripartite bay windows, double-hung windows on upper story on front façade, double-hung windows on rear façade & center hall entrance w/ transom off of 3-bay wide Gothic Revival style porch, double round arch windows in upper gable ends; 1-5 story wing on south w/ entrances on front & rear, double-hung windows, round arch double-hung windows on upper gable end, stylized round arched eyebrow windows, hood moldings on windows & doors, decorative vergeboards.
47	Sands Ave	103.9-1-13	G.R.T. Wells (1875)	ca. 1870	Classical Revival	2- story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, center hall entrance off of full porch w/ later posts, double-hung windows.
48	Sands Ave	103.1-3-6	S.O.F. Colman (1875)	ca. 1870	Gothic Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ center gable wall dormer & interior brick chimney, wood clapboard siding, brick & stone foundation, center hall entrance off of 3-bay center porch w/ replacement columns & balustrades, double-hung windows, lower-story square bay window on south side, tripartite bay window on west side, rear entrance w/ overhang & brackets.
52	Sands Ave	103.1-3-5		ca. 1880	Queen Anne	HOUSE: 2-story wood frame single-family dwelling, metal cross-gable roof w/ interior brick chimney, wood clapboard siding, brick & stone foundation, side hall entrance off of wrap-around porch w/ spandrels, turned columns, and balustrades, single & paired double-hung windows, paired round arch double-hung windows in gable ends. CARRIAGE BARN: 1.5-story wood frame carriage barn, front-gable roof w/ cupola, wood clapboard siding, haymow door, rail track doors.
55	Sands Ave	103.9-1-11		1900	Colonial Revival	1 -story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ shed dormer, vinyl clapboard siding, concrete foundation, entrance w/ fanlight off of gable portico w/ round columns, secondary entrance off of corner porch on front facade, single & paired double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
56	Sands Ave	103.1-3-4	Rev. J.W. Smith	ca. 1880	Queen Anne	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end & center gable wall dormer, wood clapboard siding, fishscale pattern wood shingle siding on upper gable ends w/ small round arch windows, stone foundation, center hall entrance w/ sidelight & transom, single & paired double-hung windows, tripartite bay window on south side.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, front-gable roof w/ cupola, vertical metal siding.</p>
57	Sands Ave	103.9-1-10	J. Rowley (1875)	ca. 1860	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end & lower rear cross-gable, vinyl clapboard siding, stone foundation, side hall entrance w/ sidelights, pilasters, & lintel, full porch w/ turned columns & balustrades, double-hung windows, eave returns.
60	Sands Ave	103.1-3-2.110		ca. 1880	Gothic Revival	2-story, 4-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior masonry chimney on north end, vinyl clapboard siding, stone foundation, side hall entrance off of porch w/ later columns & balustrades, double-hung windows.
64	Sands Ave	103.1-3-1		ca. 1895	Queen Anne	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys, wood clapboard siding, brick & stone foundation, double-door center hall entrance off of Gothic Revival style portico w/ chamfered columns & flat sawn balustrades, entrance flanked by later tripartite bay windows, double-hung windows on upper story on front façade, double-hung windows on rear façade & center hall entrance w/ transom off of 3-bay wide Gothic Revival style porch, double round arch windows in upper gable ends; 1-5 story wing on south w/ entrances on front & rear, double-hung windows, round arch double-hung windows on upper gable end, stylized round arched eyebrow windows, hood moldings on windows & doors, decorative vergeboards.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
73	Sands Ave	103.9-1-6	W. Butty (1875)	ca. 1875	no style	1.5 story 3-bay wood frame single-family dwelling w/ later 2-story wood frame addition to south, asphalt shingle side-gable roof w/ interior stone chimney, vinyl clapboard siding, stone & concrete foundation, center entrance off of porch w/ later turned columns, double-hung & small multi-pane windows on original house, secondary entrance, paired double-hung windows, & oculus window on addition, paired French doors on north end.
7-20	Sands Dock Ln	103.1-2-23	Estate of Mrs. M.L. Johnson (1875)	ca. 1840	no style	HOUSE 1: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney, wood shingle siding, stone foundation, center hall entrance w/ partial sidelights under gable overhang & 2-story octagonal portico w/ round columns & upper balustrades, single & paired double-hung windows, 1-story rear addition w/ large plate glass window overlooking pool, attached sunroom on south façade, attached 1-bay garage w/ sectional door on north end. HOUSE 2: Possible earlier barn converted into a dwelling, 2-story, 2-bay banked wood frame single-family dwelling, asphalt shingle side-gable roof w/ large center gable wall dormer, wood clapboard siding w/ wood shingle on upper gable ends, stone foundation exposed on west façade, side entrance & double-hung windows on south end, lower story casement oriel windows underneath later upper story deck accessed by sliding glass doors on east façade, lower walk-in basement entrance on south end.
7-20	Sands Dock Ln	103.1-2-23	Mrs. S.A. Sands (1875)	ca. 1875	Classical Revival	2-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, wood clapboard siding, stone foundation, side entrance off of full porch w/ later columns, double-hung windows, later deck toward rear on east side.
	Sands Dock Rd	103.1-2-25.200	B.B & S.A. Sands (1875)	ca. 1875	n/a	3-story, 3-bay brick masonry ruin of former factory, brick wall construction, stone foundation, center round arch entrance, square window openings intact on lower 2 stories.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
8	Sands Dock Rd	103.1-2-27		ca. 1899	no style	1-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance w/ fluted pilasters & architrave, double-hung windows on front façade, small stone lean-to on south w/ single & grouped double-hung windows, stone lean-to on north w/ vinyl clapboard siding & double-hung windows.
44	Schraeter's Ln	103.1-3-8	Miss A. Wright (1875)	ca. 1875	Classical Revival	2-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end, vinyl clapboard siding, concrete foundation, later multi-pane windows, dwelling has been heavily altered.
13	Shanghai Hill	103.9-1-15	Episcopal Church (1875)	ca. 1850	Gothic Revival	2-story wood frame converted church now single-family dwelling, steeply pitched asphalt shingle side-gable roof w/ lower side-gable, later shed & gable dormers, vinyl novelty siding, stone foundation, later steeply pitched vestibule entrance w/ partial sidelights, narrow multi-pane windows.
16	South Rd	103.9-2-20	B. Roe (1875)	ca. 1880	Queen Anne	HOUSE: 1-story, 2-bay wood frame single-family dwelling, asphalt shingle hipped-gable roof w/ lower cross gables, gable dormers, & interior brick chimney, wood clapboard siding, brick & stone foundation, side hall entrance w/ sidelight & transom under decorative trim overhang w/ brackets, double-hung windows w/ lintels & sills, square bay windows on front façade & south side, decorative vergeboards. GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof w/ gable dormers on north side, wood clapboard siding.
508	South Rd	103.3-3-73	Capt. Sears (1875)	ca. 1870	Classical Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance w/ sidelights off of wrap-around porch enclosed on north side, double-hung windows. BARN: 1-story, 1-bay wood frame barn, asphalt shingle gable roof, wood clapboard siding.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
516	South Rd	103.3-3-4	J. Lester (1858)	ca. 1850	no style	HOUSE: Original 1.5 story, 3-bay wood frame single-family dwelling, later 2-story addition to north, asphalt shingle front-gable roof w/ lower side-gable, vinyl novelty siding, stone & concrete foundations, side hall entrance w/ sidelights, double-hung windows, eyebrow windows, incorporated garage on north side. BARN: 1-story wood frame barn, asphalt shingle side-gable roof w/ vented cupola, wood clapboard siding, stone foundation, sliding rail track door & haymow door.
542	South Rd	103.3-2-34	Old Dina (1858)	ca. 1850	Classical Revival	HOUSE: Original 2-story, 3-bay wood frame-family single dwelling, later 2-story addition to north, asphalt shingle side-gable roof w/ lower rear cross-gable & exterior brick chimney on north end, vinyl clapboard siding, stone foundation, side hall entrance off of later full porch, double-hung windows. GARAGE: 1-story, 2-bay wood frame garage, low-pitched asphalt shingle front-gable roof, wood clapboard siding.
568	South Rd	103.3-2-3.200	D. Lester (1858)	1780	Federal	1-story, 5-bay wood frame single-family dwelling, metal side-gable roof w/ interior brick chimney on north end & exterior brick chimney on south end, wood clapboard siding, stone foundation, center hall entrance off of later gable portico, double-hung windows, later multi-pane windows.
574	South Rd	103.3-2-2	C. Rhodes (1875)	ca. 1880	Queen Anne	2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, wood clapboard siding, varied pattern wood shingle siding in upper gable end, stone foundation, side hall entrance off of wrap-around porch w/ turned columns, sprandrels, & balustrades on north side, double-hung windows, 2-story bay windows toward rear on north & south sides, 1-story rear addition.
602	South Rd	103.3-2-8	Mrs Hallock (1875)	ca. 1875	no style	2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, brick & stone foundation, entrance toward front on south side off of later summer porch, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
608	South Rd	103.1-3-35.100	G. Hallock (1875)	ca. 1800	Federal	HOUSE: 1-story wood frame single-family dwelling, asphalt shingle gable roof w/ interior brick chimney & later shed dormer, wood clapboard siding, stone foundation, exterior vestibule entrance, double-hung windows, rear lean-to addition w/ secondary entrance, later rear deck. OUTBUILDING: 1-story wood frame outbuilding converted to hen house, metal gable roof, wood novelty siding, stone foundation.
613	South Rd	103.1-3-43	J. Myers (1875)	ca. 1850	Classical Revival	HOUSE: 1-story, 3-bay banked wood frame single-family dwelling, asphalt shingle roof w/ shed dormer, asbestos shingle siding, stone foundation, center entrance on south end off of full porch, double-hung windows, walk-in basement entrance. GARAGE: 1-story wood frame garage, asphalt shingle gable roof, wood flush board siding.
617	South Rd	103.1-3-44.100	J. Myers (1875)	ca. 1840	Federal	1-story, 2-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ concrete chimney on south end, vinyl clapboard siding, stucco sided stone & foundation, side-hall entrance w/ partial sidelights & transom off of later gable portico, casement bay window, side entrance off of gable portico on south façade, double-hung windows on north & south facades, lower 1-story attached garage w/ sectional garage bay door on south end.
634	South Rd	103.1-3-31		ca. 1920	Dutch Colonial Revival	1-story, 4-bay wood frame single dwelling, asphalt shingle gambrel roof w/ interior brick chimney & large shed dormers on front & rear, vinyl clapboard siding, concrete foundation, side entrance off of full porch w/ tapered columns & kneewalls, double-hung windows, large tripartite bay window, 1-story wing on north.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
16	South St	108.12-5-13	Benjamin Sarles House	ca. 1870	Second Empire	<p>HOUSE: 2-story wood frame single-family octagon dwelling, later fishscale pattern composite shingle Mansard roof w/ segmental arch dormers & interior brick chimney, wood clapboard siding, stone foundation, original main recessed entrance located on southeast & obscured by later enclosed porch, paired double-hung windows, tripartite oriel window on southwest, square bay window on east, later hip-gable 2-story kitchen wing on west w/ interior brick chimney & single double-hung windows, rear portico entrance on later 1-story rear octagonal addition, frieze & eave brackets.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof, wood clapboard siding, sectional garage bay door, man door, double-hung windows.</p> <p>BARN: 1-story metal barn, metal gambrel roof & siding, sectional bay doors, man door w/ double-hung window.</p>
17	South St	108.4-6-21.111		1932	Cape Cod	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ center gable wall dormer & lower rear cross-gable, vinyl clapboard siding, stucco sided foundation, center entrance off of gable portico w/ tapered square columns, double-hung windows, paired double-hung windows on upper gable ends, side entrance w/ gable overhang toward rear on west façade, enclosed porch on east façade w/ entrance on north end, walk in basement entrance.</p> <p>SHED: 1-story, 1-bay wood frame shed w/ asphalt shingle roof & vinyl clapboard siding, sectional shed door.</p>
19	South St	108.4-6-5.100		ca. 1880	Queen Anne	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, concrete foundation, side hall entrance off of full porch w/ turned columns & spindle balustrades, double-hung windows, later 1-story addition w/ paired double-hung windows on rear.</p> <p>GARAGE: 1-story wood frame garage, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, 2 sectional garage bay doors, entrance, double-hung windows.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
21	South St	108.4-6-4		ca. 1900	no style	1-story wood frame single-family dwelling, asphalt shingle front-gable roof w/ lower cross-gable & exterior brick chimney on east side, vinyl novelty siding, stone foundation, entrance off of porch toward rear on east façade, double-hung windows, 1-story addition w/ paired & grouped casement windows.
23	South St	108.4-6-3		1955	Ranch	1-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney, composite shingle siding, concrete foundation, center entrance w/ paired & grouped double-hung windows on front façade, single double-hung windows on west façade.
27	South St	108.4-6-2		1960	Ranch	1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower cross hip-gables on front & rear, vinyl clapboard siding, concrete foundation, side entrance & tripartite oriel on front ell
31	South St	108.4-6-1.200		ca. 1900	no style	2-story wood frame single-family dwelling, asphalt shingle front-gable roof, vinyl clapboard siding, concrete foundation, center entrance on exterior concrete block vestibule, enclosed upper story porch, double-hung windows.
47	South St	108.4-7-19	P. Dubois (1858)	ca. 1850	Italianate	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, asbestos shingle siding, concrete foundation, side hall entrance, double-hung windows, paired eave brackets, 1-story rear addition. BARN: 1-story banked wood frame barn, asphalt shingle gable roof, wood novelty siding, brick & stone foundation.
50-52	South St	108.4-2-61	I. Coutant (1875)	ca. 1875	Gothic Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, metal side-gable roof w/ center gable wall dormer, vinyl clapboard siding, stone & concrete foundation, center hall entrance w/ partial sidelights off of full . w/ turned columns & balustrades, single & paired double-hung windows. BARN: Small 1-story wood frame barn, metal side-gable roof, large center opening flanked by small windows, double-hung windows.
1	Stuart Dr	109.1-1-27.200		ca. 1850	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, composite clapboard siding, stone foundation, side hall entrance off of full porch, double-hung windows, tripartite bay window on south façade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
9	Stuart Dr	109.1-1-27.400		ca. 1850	Classical Revival	2-story, 5-bay banked wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, center hall entrance, walk-in basement entrance, double hung windows, later 1-story rear addition.
1-4	Tally Ho Ln	108.4-5-1.100	L.S. Carpenter (1875)	ca. 1870	Gothic Revival	HOUSE: 2-story, 5-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ center gable wall dormer & interior brick chimneys on opposing ends, wood clapboard siding, stucco sided brick & stone foundation, center hall entrance w/ partial sidelights & transom off of full porch porch w/ chamfered columns & brackets, north & south end of porch enclosed, double-hung windows, quatrefoil oculus in upper gable dormer, small 1-story wing on north, rear enclosed stairwell accessing upper story, rear 1-story addition w/ enclosed glass porch. BARN 1: 1-story wood frame barn, asphalt shingle front-gable roof w/ interior brick chimney, wood clapboard siding, sectional garage bay door, haymow door, multi-pane windows. BARN 2: 1-story wood frame banked barn, asphalt shingle gable roof, vinyl clapboard siding, brick & stone foundation, sectional garage bay door & man door on south end, sectional garage bay doors & man door on east facade's lower level.
1106	US Route 9W	108.4-5-28.200		ca. 1880	Gothic Revival	2-story, 5-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ gable wall dormers & interior brick chimney, vinyl clapboard siding, stone foundation, center hall entrance off of later 3-bay wide porch, double-hung windows, 1-story wood frame addition on south end & off southwest corner, rear entrance off of stone patio.
1108-1116	US Route 9W	108.4-5-29		ca. 1900	Classical Revival	2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, stucco sided, concrete foundation, primary entrance off of later porch on 1-story wing on west, rear entrance on east facade, single & paired double-hung windows, tripartite bay window on south facade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1209	US Route 9W	108.12-5-11	St. Mary's Roman Catholic Church	1922	Gothic	1-story brick masonry church, slate shingle roof, brick wall construction w/ cast stone asents & courses, brick & stone foundation, center pointed arch entrance w/ cast stone surround & flanked by small pointed arch stained glass windows, large pointed arch stained glass windows on north & south facades between wall buttresses, multi-story crenelated belfry tower w/ gargoyle & wall buttresses on northeast corner, niche statuary atop of wall buttresses flanking entrance.
1211	US Route 9W	108.12-5-10	I. Carpenter (1875)	ca. 1840	Italianate	HOUSE: 2-story, 3-bay wood frame single-family dwelling, metal side-gable roof w/ interior brick chimney on north end, wood clapboard siding, stone foundation, side hall entrance w/ later gable portico, double-hung windows, complex timber frame window in upper gable end on south, 1-story south wing w/ metal roof & interior brick chimney, later full facade patio & stone wall, cornice brackets. GARAGE: 1-story, 1-bay wood frame garage, metal side-gable roof, sectional garage bay door.
1213	US Route 9W	108.12-5-9	I. Drake (1875)	ca. 1850	Gothic Revival	HOUSE: 2-story, 4-bay wood frame two-family dwelling, originally 3-bay wide w/ side hall entrance, 4th bay on south end added in late 19th century, asphalt shingle cross-gable roof w/ interior brick chimney on north end, vinyl clapboard siding, stone foundation, side hall entrance w/ sidelights & transom off of full porch w/ turned columns & later balustrades, double-hung windows, paired double-hung window over tripartite bay window, pointed arch double-hung window in upper gable end. GARAGE: 1-story wood frame garage w/ asphalt shingle gable roof, vertical wood panel siding, double-door entrance on north end.
1215	US Route 9W	108.12-5-8	J. Achbertson (1875)	ca. 1840	Greek Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on north end, vinyl clapboard siding, stone foundation, side hall entrance off of full enclosed porch, double hung windows, 1-story rear addition, frieze band.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1217	US Route 9W	108.12-5-7	Methodist Church (1858) Catholic Church (1875)	1825	Federal	2-story wood frame converted church, now a commercial building, asphalt shingle front-gable roof, vinyl clapboard siding, stone & concrete foundation, lower story altered on front façade by added storefront w/ large plate glass windows & sectional bay door & attached garage w/ sectional bay door, other alteration is sectional garage bay door w/ overhang & side door on north façade, double-hung windows w/ pilasters & cornice on front façade, double-hung windows on north & south facades, paired eave brackets.
1251	US Route 9W	108.12-4-20	Marlboro Free Library	1978	Brutalist	1-story concrete block masonry library, flat roof of unknown synthetic material, masonry block wall construction, concrete foundation, glass vestibule entrance & plate glass windows on front façade, rear entrance off of patio courtyard, plate glass windows on rear façade.
1259	US Route 9W	108.12-4-19		1916	Classical Revival	2-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ round arch eyebrow dormer, vinyl clapboard siding, stone foundation, side hall entrance off of full porch w/ round arch openings & knee walls, grouped double-hung windows & tripartite bay window on front facade, double-hung windows & tripartite bay window on south facade.
1261	US Route 9W	108.12-4-18	J. Kniffen (1875)	1850	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end & low-pitched shed roof on rear, wood clapboard siding, stone foundation, side hall entrance w/ partial sidelights off of full porch w/ turned columns & small brackets, double-hung windows.
1263	US Route 9W	108.12-4-16	C. Brower (1875)	ca. 1850	Queen Anne	2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance off of corner veranda w/ turned columns & spindle balustrades, double-hung windows, 2-story tripartite bay window on front facade.
1278	US Route 9W	108.4-3-20	cemetery			
1282	US Route 9W	108.4-3-21	cemetery			

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1283	US Route 9W	108.12-4-15	D.B. Ventress (1875)	ca. 1820	Federal	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end, wood clapboard siding, stone foundation, side hall entrance framed by fluted pilasters & architrave w/ partial sidelights & tracery transom, full porch w/ square columns & cornice brackets, double-hung windows w/ architraves, quarter-round windows in upper gable ends, 1.5-story wing on south w/ double-hung windows & eyebrow windows.
1287	US Route 9W	108.12-4-11		1900	Foursquare	2-story, 3-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ hip-dormer & interior brick chimney, wood shingle siding on upper story & vinyl clapboard siding on lower story, concrete foundation, side hall entrance off of full porch w/ brick piers & round columns, double-hung windows.
1290	US Route 9W	108.4-3-22	Judge S. Stilwell (1858 A. Stillwell (1875)	ca. 1853	Second Empire	2-story, 5-bay wood frame former single-family dwelling, slate shingle Mansard roof w/ 3 brick chimneys & gable dormers, vinyl clapboard siding, stone & concrete foundations, dwelling has undergone extensive alterations & additions, center entrance under a porte-cochère on former enclosed former veranda w/ double-hung windows & tripartite oriel window on south end, original cornice brackets, large 2-story rear addition w/ basement garage on south end.
1292	US Route 9W	108.4-3-23		1929	Bungalow/Craftsman	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, center entrance off of cross-gable porch w/ stone knee walls & square columns, double-hung windows, square bay window & secondary entrance on south façade.
1294	US Route 9W	108.4-3-24		ca. 1920	Craftsman Cottage	1-story wood frame single-family dwelling, asphalt shingle cross-hip gable roof w/ interior brick chimney, vinyl novelty siding, stone & brick foundation, entrance off of corner porch on north facade, double-hung windows, upper story deck & basement garage toward rear on north facade, secondary entrance off of porch n south facade.
1298	US Route 9W	108.4-3-25.110		ca. 1920	Commercial	1-story wood frame commercial building, flat roof of unknown synthetic material, wood shingle & vinyl novelty siding, concrete foundation, 2 separate entrance w/ large plate glass windows under wood shingle overhang..

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1300	US Route 9W	108.4-3-25.110		ca. 1900	Commercial	2-story, 5-bay wood frame commercial building, flat roof of unknown synthetic material, vinyl novelty siding, concrete foundation, storefront w/ center entrance flanked by paired plate glass windows, under wood shingle overhang, double-hung windows on the upper story.
1304	US Route 9W	108.4-3-25.110		ca. 1900	Commercial	1-story wood frame commercial building, metal gable roof w/ stepped gable, vinyl novelty siding, concrete foundation, storefront for 2 businesses w/ 2 separate entrance & large plate glass windows under wood shingle overhang.
1305	US Route 9W	108.12-3-25	Mrs. E. Doyle (1875)	ca. 1850	Classical Revival	2-story, 3-bay wood frame two-family dwelling w/ lower 2-story wing, asphalt shingle side-gable roof w/ interior brick chimney on south end & gable dormers, wood clapboard siding, stone foundation, side hall entrance off of later full porch double-hung windows & secondary side entrance w/ double-hung windows on front facade, double-hung windows on north & south facades.
1307	US Route 9W	108.12-3-24		1890	Colonial Revival	2-story, 3-bay wood frame multi-family dwelling, flat roof of unknown synthetic material & exterior concrete chimney, vinyl clapboard siding, stucco sided stone foundation, center entrance w/ partial sidelights off of hip-gable portico w/ round columns, double-hung windows on front, north, & south facades.
1309	US Route 9W	108.12-3-23		1890	Queen Anne	2-story, 2-bay wood frame single-family dwelling, low-pitched asphalt shingle roof w/ exterior concrete chimney, vinyl clapboard siding, stone foundation, side hall entrance off of full porch w/ turned columns & spindle balustrades, double-hung windows on front, north, & south facades, square bay window toward rear on south façade.
1311	US Route 9W	108.12-3-12	Marlboro Free Library	1921	Classical Revival	BUILDING: 1-story, 3-bay brick masonry former library building, asphalt shingle cross-gable roof, stucco sided, concrete foundation, center entrance off of gable portico w/ entablature & round columns, entrance flanked by double-hung windows, picture windows on east & west facades. eave returned on east & west gable ends. MONUMENT: Granite monument w/ in memoriam brass plaque listing village residents who served in World War I.
1313	US Route 9W	108.12-3-11		ca. 1950	Commercial	2-story, 3-bay brick masonry commercial building, flat roof of unknown synthetic material, brick wall construction, concrete foundation, center entrance, paired double-hung windows on lower story, single double hung-windows on upper story.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1316	US Route 9W	108.4-3-26.100		1965	Commercial	1-story wood frame garage, low-pitched gable roof of unknown synthetic material, vinyl clapboard siding, concrete foundation, sectional garage bay doors & man door w/ gable overhang on southwest end, sectional garage bay door along mid-point of northwest facade w/ 2 man door entrances.
1320	US Route 9W	108.4-3-27	Sumers (1891)	ca. 1891	Commercial	3-story, 3-bay wood frame commercial/domestic building, flat roof of unknown synthetic material, vinyl clapboard siding, stone foundation, storefront consists of entrance flanked by large plate glass windows under awning, side entrance accessing upper stories, double-hung windows on upper stories, cornice w/ panels between brackets & dentils.
1326	US Route 9W	108.4-3-28	Hartshorn Building	1897	Commercial	3-story, 4-bay brick masonry commercial row building, flat roof of unknown synthetic material, brick wall construction, stone foundation, storefront consists of double glass doors & large plate glass window under an awning, double-hung windows on front & south facades, secondary entrance toward rear on south facade, brick cornice & corbeling, bluestone name & date plaque.
1330	US Route 9W	108.4-3-3.100	Mullin's Hotel (1858)	ca. 1850	Commercial	HOTEL: Comprised of a series of attached buildings; on south end is a 3-story, 2-bay wood frame building w/ low-pitched asphalt shingle roof, aluminum clapboard siding, stone foundation, double-hung windows, lower story brick front w/ entrance & paired double-hung windows under awning; directly north is a 2-story, 6-bay wood frame Second Empire style building. slate shingle Mansard roof w/ segmental arch dormers & cupola, vinyl clapboard siding, stone foundation, 2-story porch w/ turned columns, balustrades, spandrels & scroll sawn brackets, upper story porch accessed by 2 entrances at either end, 3 lower story entrances, double-hung windows, paired scroll sawn eave brackets & decorative frieze panels; 1-story wood frame former billiards & bowling alley component of hotel, 3 separate entrances w/ double-hung windows & large pane storefront windows under shed roof overhang. GARAGE: 1-story wood frame garage, flat roof w/ parapet wall, vinyl clapboard siding, concrete foundation, 2 sectional garage bay doors w/ adjoining man doors, series of multi-pane windows beneath parapet wall.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1331	US Route 9W	108.12-2-29	J. Badner (1875)	ca. 1850	Commercial	<p>HOUSE/COMMERCIAL BUILDING: 3-story wood frame dwelling/commercial building originally located on corner of Western Avenue & US Route 9W, asphalt shingle side-gable roof, wood shingle siding, stone & concrete foundations, storefront w. recessed entrance & transom, large plate glass windows, enclosed upper story porch, double-hung windows on original dwelling, quarter round windows on upper gable end, paired eave brackets; 1-story concrete block masonry additions to north w/ sectional garage doors.</p> <p>GARAGE: 1.5-story wood frame garage, asphalt shingle side-gable roof w/ center gable wall dormer, wood novelty siding, stone foundation, later sectional garage bay doors, man door, haymow door, small multi-pane window in dormer.</p>
	US Route 9W		Concrete Highway Bridge	ca. 1930	Transportation	
1347-1351	US Route 9W	1082.12-2-28	DuBois Grist Mill site N.W. Wright Feed Mill (1886)	ca. 1780	Industrial	<p>COMMERCIAL BUILDING: 2-story wood frame automotive commercial building, flat roof of unknown synthetic material w/ parapet wall, vinyl clapboard siding, concrete foundation, center door w/ large plate glass windows on front facade, double-hung windows toward front & sectional garage bay doors toward rear on north facade.</p> <p>STORAGE BUILDING: FEED MILL RUIN:</p>
1348	US Route 9W	108.4-3-2.100	Marlborough Fruit Preserving Company (1886)	ca. 1886	Industrial	2-story wood frame commercial building, metal front-gable roof w/ exterior brick chimney toward rear on south side, wood novelty siding, brick & stone foundation, double-door center entrance w/ paired double-hung windows on front façade, several double-door entrance on north & south facades, full porch along north façade, rear exterior vestibule entrance, double-hung & casement windows, complex 2-story decking on south façade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1349	US Route 9W	108.12-2-24	N.W. Wright House	ca. 1850	Queen Anne	<p>HOUSE: Northern 2-story, 3-bay portion of the wood frame single-family dwelling is the original house, later 2-story, 3-bay section added, low-pitched asphalt shingle gable roof, wood clapboard siding, stone & brick foundation, original house w/ side hall entrance off of 2-bay wide porch w/ turned columns, spandrels & balustrades, later addition w/ side hall entrance off of portico w/ turned columns & spandrels, rear porch w/ turned columns & balustrades, double-hung windows, later 2-story wing on south w/ paired casement windows on lower story.</p> <p>CARRIAGE HOUSE: 1-story, 4-bay wood frame carriage house, asphalt shingle hip-gable roof w/ gable haymow dormer & exposed rafters ends, wood clapboard siding, 4-garage bay doors on south facade, double-hung windows, man door on west facade.</p>
1355	US Route 9W	108.12.2-27	DuBois Grist Mill site N.W. Wright Feed Mill (1886)	ca. 1850	Industrial	
1359	US Route 9W	108.12-2-26	Knapp House (1875)	ca. 1875	Classical Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys on opposing ends & lower rear cross-gable, asbestos shingle siding, stone foundation, center hall entrance w/ sidelights off of full porch w/ turned columns, scroll sawn brackets & balustrades, double-hung windows, eave returns.
1361	US Route 9W	109.1-4-24	Birdsall House (1875)	ca. 1875	Second Empire	<p>HOUSE: 2-story, 5-bay wood frame two-family dwelling, varied patterned slate shingle Mansard roof w/ flat roof dormers & exterior stone chimney on north end, wood clapboard siding, stone foundation, center hall entrance off of full porch w/ stone knee wall & round columns, double-hung windows, square & tripartite bay windows on south facade, paired cornice brackets.</p> <p>GARAGE: Large 2-story, 5-bay wood frame garage, wood clapboard siding, concrete foundation, low-pitched asphalt shingle side-gable roof w/ exterior brick chimney on south end, 4 sectional garage bay doors w/ center man door, double-hung windows, upper story haymow door, casement windows on south end.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1365	US Route 9W	109.1-4-23	H. Covert (1891)	ca. 1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance off of full porch w/ turned columns & spindle balustrades, double-hung windows, square bay window toward rear on south facade, 1-story rear addition.
1367	US Route 9W	109.1-4-22	Jno L. Debois (1891)	ca. 1875	Classical Revival	2-story, 2-bay brick masonry & wood frame single family dwelling, asphalt shingle side-gable roof, brick wall construction on lower story & vinyl clapboard on upper story, brick & stone foundation, side entrance on later 1-story addition on south & rear, small 1-story ell w/ hip-gable roof on front, casement bay windows on front facade's lower story, double-hung windows.
1400	US Route 9W	109.1-3-38	S. Harris (1858)	ca. 1850	Classical Revival	2-story, 3-bay wood frame single-family dwelling with addition, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance, front-gable bay on front of extension, double-hung windows.
1401	US Route 9W	109.1-4-17	J. Schults (1875)	ca. 1860	Greek Revival	HOUSE: 1.5- story, 3-bay wood frame single-family dwelling, single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete chimney on north end & interior brick chimney on south, aluminum clapboard siding, stone foundation end, side-hall entrance off of enclosed full porch, double-hung windows, eyebrow windows, large shed dormer on rear. GARAGE: 1-story wood frame garage, asphalt shingle front-gable roof, wood novelty siding, sectional garage bay door.
1403	US Route 9W	109.1-4-15	J. Rose (1875)	1857	no style	2-story wood frame single-family dwelling, asphalt shingle gable roof, wood shingle siding, concrete & stone foundations, tripartite bay windows, casement windows, double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1406	US Route 9W	109.1-3-1.330	Col. Louis DuBois Homestead S. Harris (1875)	1756	Colonial	<p>HOUSE 1: 1-story, 5-bay wood frame single family dwelling, asphalt shingle Jerkinhead roof w/ interior brick chimneys on opposing ends & gable dormers, wood clapboard siding, stone foundation, center hall entrance off of later porch w/ spandrels & balustrades, double-hung windows, paired double-hung windows & round arch window on west end, lean-to addition on east end w/ front & rear side porches.</p> <p>HOUSE 2: 2-story, 3-bay wood frame single-frame dwelling, metal side-gable roof w/ interior brick chimney on south end, wood board-&batten siding, stone foundation, entrance flanked by narrow double-hung windows on single, paired & grouped double-hung windows on front façade, double-hung windows on north, south & rear facades, attached car port on south.</p> <p>GARAGE 1: 1-story, 2-bay wood frame garage, metal shed roof, wood novelty siding, concrete foundation, sectional garage bay doors on front & double-hung windows on rear.</p> <p>GARAGE 2: 1-story, 1-bay wood frame garage, metal gable roof, wood novelty siding, concrete foundation, sectional garage bay door on front, double-hung windows.</p> <p>BARN 1: Large 2-story wood frame barn, metal side-gable roof, wood board-&batten siding, stone foundation. GRANARY: Wood frame granary, asphalt shingle front-gable roof w/ vented cupola, wood novelty siding, stone foundation, vertical granary doors on west façade.</p> <p>CORN CRIB: 1-story wood frame corn crib, metal gable roof w/ exposed rafter ends, wood slat sided slanted walls, brick piers, entrance on north end.</p> <p>AGRICULTURAL FIELDS & ORCHARDS</p>
1435	US Route 9W	109.1-4-8.100	O. Phillips (1875)	ca. 1860	Classical Revival	2-story, 2-bay wood frame two-family dwelling, asphalt shingle front-gable roof, vinyl clapboard siding, stucco sided stone foundation, side hall entrance off of patio, double-hung windows, enclosed 1-story porch on west side w/ secondary entrance & casement windows.
1465	US Route 9W	109.1-1-38.100	J. Terwilliger (1875)	ca. 1850		Access denied.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1514-1516	US Route 9W	109.1-2-19	Mrs. D. Sand (1875)	ca. 1875	Gothic Revival	2-story, 5-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end & center gable wall dormer, asbestos shingle siding, stone foundation, center hall entrance w/ sidelights off of 3-bay wide porch, double-hung windows, quarter round windows in upper gable ends, later sliding glass doors on south façade, small 1-story rear addition,
1525	US Route 9W	109.1-1-3	B.A. Rose (1875)	ca. 1875	Gothic Revival	HOUSE: 2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable wall dormers on front & rear, vinyl clapboard siding, stone foundation, center hall entrance w/ partial sidelight off of 3-bay wide porch, double-hung windows, walk-in basement entrance on tripartite bay window on south façade. BARN: 1.5-story wood frame barn, asphalt shingle front-gable roof, vinyl novelty siding, entrance & double-hung windows on south façade, later attached machine shed on west.
1526	US Route 9W	108.12-2-57		1890	no style	2-story wood frame multi-family dwelling, asphalt shingle side-gable roof, aluminum clapboard siding, stone & brick foundations, various size single & paired double-hung windows, later 2-story addition on front facade & to east, dwelling likely originally had center hall entrance facing south.
1532	US Route 9W	103.3-5-22		1890	no style	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete chimney on north end, vinyl clapboard siding, stone foundation, center hall entrance off of later full porch, double-hung windows. SHED: Manufactured metal shed w/ sliding doors.
1542	US Route 9W	103.3-5-1		1875	Classical Revival	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior chimney & shed roof dormer on rear, vinyl clapboard siding, concrete foundation, primary entrance on 1-story front addition, double-hung windows, 1-story rear addition. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, wood novelty siding, 2 sectional garage bay doors.
1557	US Route 9W	103.3-4-45		1875	Gothic Revival	2-story, 5-bay wood frame single-family home, asphalt shingle side-gable roof w/ center gable wall dormer & exterior brick chimney on south end, vinyl clapboard siding, brick & stone foundation, center hall entrance off of gable portico, double-hung windows, side entrance off of deck on south façade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1559	US Route 9W	103.3-4-44		1890	no style	1-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ gable wall dormers & exterior concrete chimney on north end, vinyl clapboard siding, concrete & stone foundations, off set entrance on front facade off of porch w/ turned columns, entrance off of porch on south facade of later addition, double-hung windows & picture window on front facade of original dwelling, multi-pane oriel window & horizontal casement window on later addition, later 1-story wood frame wing on north end.
1564	US Route 9W	103.3-3-58	T. Sears (1875)	ca. 1875	Classical Revival	HOUSE: 2-story, 3-bay banked wood frame single-family dwelling, metal side-gable roof w/ interior brick chimney, wood clapboard siding, brick & stone foundation, side hall entrance w/ partial sidelights off of full porch w/ slender chamfered columns & brackets, lower story full length windows w/ storm windows on front facade, double-hung windows, walk-in basement entrance on south facade, side hall entrance & double-hung windows on rear facade, rear full porch w/ slender chamfered columns & brackets, later grouped double-hung windows on south facade's lower story, 1-story wing on north w/ double hung windows & side entrance on north. SHED: 1-story banked wood frame shed, asphalt shingle gable roof, wood clapboard siding stone foundation.
1584	US Route 9W	103.3-3-61	W. Rhodes (1875)	ca. 1875	Stick Style	1-story, 3-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, composite clapboards, stone foundation, side hall entrance off of full porch, double-hung windows, pendant-&-crossbar motif, eave brackets, 1-sty rear addition & deck.
1595	US Route 9W	103.3-4-38.100	F. Greig (1875)	ca. 1875	no style	2-story brick masonry & wood frame two-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, brick wall construction & vinyl clapboard siding, stone & concrete foundations, 1-story addition on front w/ side entrance accessing upper story & entrance of north end under portico accessing lower story, single & paired double-hung windows.
1613	US Route 9W	103.3-4-20		ca. 1891	Queen Anne	2-story, 2-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance w/ sidelights & transom off of full porch, tripartite bay window on south facade.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1615	US Route 9W	103.3-4-18		ca. 1891	Classical Revival	2-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ lower-cross gable & exterior brick chimney on north side, vinyl clapboard siding, brick & stone foundation, side-hall entrance off of full porch, double-hung windows, tripartite bay window on south facade.
1651	US Route 9W	103.3-4-15.100		1910	Classical Revival	2-story, 3-bay banked wood frame single-family dwelling, metal front-gable roof w/ lower cross-gable & interior brick chimney, wood clapboard siding, stone & concrete block foundation, center hall entrance w/ gable overhang, double-hung windows, walk-in basement entrance on north façade.
1657	US Route 9W	103.3-4-14	J. Lyons (1858)	ca. 1858	Italianate	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof, wood clapboard siding, stone foundation, double-door center hall entrance off of full porch w/ chamfered columns & scroll sawn brackets, French windows on lower story & double-hung windows on upper story's front facade, double-hung windows on north and south facades, double-hung arched window on upper gable ends, walk-in basement entrance on south end, 1-story wing on south w/ separate entrance & double-hung windows.
1690	US Route 9W	103.3-3-71	School House (1858)	ca. 1900	Classical Revival	HOUSE: 1-story wood frame former school house, now single family dwelling, asphalt shingle hip-gable roof w/ lower projecting cross-gable, vinyl clapboard siding, stone foundation, center entrance flanked by tripartite oriel windows, paired double-hung windows on front facade, single double-hung windows on north & south facades. SHED: 1-story wood frame shed w/ asphalt shingle gable roof & plywood siding.
1724	US Route 9W	103.3-2-67	W. O'Neil (1891)	1889	Classical Revival	HOUSE: 2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on north end, vinyl clapboard siding, stone foundation, center hall entrance off of veranda w/ turned columns & balustrades, single & paired double-hung windows on front facade, double-hung windows on north & south facades, tripartite bay window toward front on south facade. GARAGE: 1-story masonry & wood frame banked garage, asphalt shingle side-gable roof, composite shingle siding, concrete block foundation, double-hung windows, 2 sectional garage bay doors.
	US Route 9W	103.1-216.100	orchard			

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1725	US Route 9W	103.3-1-12	Hallock House? Ship Lantern Inn	ca. 1780	no style	<p>RESTAURANT: 2-story wood frame & masonry restaurant, asphalt shingle cross-gable roof w/ exterior stone chimneys & shed wall dormers, vinyl clapboard siding, stone & concrete foundations, exterior vestibule side ,entrance w/ double-hung windows, center entrance w/ sidelights & flanked by grouped double-hung windows on east façade, later 1-story stone wing on north w/ vinyl clapboard siding on upper gable end & series of double-hung windows, 1-story concrete block wing on south w/ double-hung windows & upper deck.</p> <p>HOUSE: 2-story, 3-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney sided in vinyl clapboard on north end, vinyl clapboard siding, stone foundation, center hall entrance off of partially enclosed porch & double-hung windows on front façade, upper story entrance & double-hung windows on north end, double-hung windows on south end, short double-hung windows on west façade above later attached 3-bay attached garage w/ sectional doors.</p>
1770-1772	US Route 9W	103.3-2-1	N. Hallock (1858) Old Carlton Inn	ca. 1830	Classical Revival	<p>HOUSE: 2-story, 6-bay wood frame single family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on southeast end & on northwest end of 2-story wing, vinyl clapboard siding, stone foundation, side hall entrance off of gable portico, double-hung windows, two 2-story wings to northwest w/ double-hung windows, 1-story lean-to addition at rear of far northwestern wing.</p> <p>MOTEL: 1-story motels w/ multiple units arranged in semi-circular pattern, asphalt shingle gable roof, vinyl clapboard siding, each unit w/ own entrance & double-hung windows.</p>
1801-1805	US Route 9W	103.1-4-5.100	Hallock's Mill Cluett Schantz Memorial Park	ca. 1800	industrial	mill ponds and raceways
1840	US Route 9W	103.1-3-59	Friends Church (1858)	ca. 1950	no style	1-story wood frame single-family dwelling, asphalt shingle front gable roof w/ exterior brick chimney on south side, wood shingle siding, vinyl clapboard siding in upper gable ends, stone foundation, casement windows off set entrance on later gable addition on front w/ vertical wood paneling & double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
1867	US Route 9W	103.1-4-1	Wm. Rash (1891)	1890	no style	HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete chimney on north end, asbestos shingle siding, stone foundation, primary entrance on north end of later enclosed full porch w/ double-hung windows, double-hung windows on front, north, & south facades. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle gable roof, vinyl clapboard siding, 2 sectional garage bay doors.
4	Watson Ave	103.1-3-14	T.J. Handley (1875)	ca. 1875	no style	2-story wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete & stone foundation, side hall entrance w/ sidelights under later upper story deck accessed by sliding glass doors double-hung windows on front facade, double-hung & casement windows on north facade, sliding glass door entrance & double-hung windows on south facade.
8-10	Watson Ave	103.1-3-15	B.F. Townsend (1858) O.C. Hill (1875)	ca. 1850	Classical Revival	2-story, 6-bay wood frame two-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimneys, vinyl clapboard siding, brick & stone foundation, 2-story & 3-bay wide original dwelling on south w/ side-gable roof & side entrance w/ sidelights, later 2-story & 3-bay wide front-gable addition w/ side hall entrance on north, double-hung windows, full façade porch w/ later columns & balustrades, eave returns. II façade porch w/ later columns & balustrades, eave returns.
12	Watson Ave	103.1-3-23	Rev. Dr. Meyers/Glenside Seminary (1875)	ca. 1875	Gothic Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, brick & stone foundation, side hall entrance off of full porch w/ turned columns, brackets & balustrades, double-hung windows, 1-story, 1-bay wing on north.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
25	Watson Ave	103.3-2-19	George Hallock (1858)	ca. 1850	Italianate	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimneys, wood clapboard siding, brick & stone foundation, center hall entrance w/ segmental arch transom off of full porch w/ slender square columns & scroll sawn bracket, on east facade, center hall entrance w/ sidelights & transom off of portico w/ slender square columns & scroll sawn brackets on west facade, segmental arch double-hung windows on east, west, & south facades, 1.5-story wing on south w/ interior brick chimney & double-hung windows, 1-story addition w/ double-doors & segmental arch double-hung windows, mold edge cornice.</p> <p>GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle hip-gable roof, sectional garage bay doors.</p>
29	Watson Ave	103.3-2-20.110	Hallock (1875)	1892	Queen Anne	<p>HOUSE: 2-story, 2-bay wood frame single-family dwelling, asphalt shingle front-gable roof w/ lower cross hip-gable roof over 2-story bay windows on north & south, wood shingle siding on upper gable ends, vinyl clapboard siding, brick & stone foundation, side hall entrance w/ small stain glass window off of veranda w/ turned columns, balustrades & spandrels, lower story tripartite bay window on front facade, 2-story tripartite bay window on north & south facades, double-hung windows.</p> <p>BARN: 2-story wood frame barn, asphalt shingle gable roof w/ lower cross-gable, wood novelty siding, stone foundation, track rail doors & haymow door on north facade, single & paired small pane windows.</p> <p>GARAGE: 1.5-story, 2-bay wood frame garage, asphalt shingle side-gable roof, vinyl clapboard siding, small & large sectional garage bay doors.</p>
2	West St	108.12-3-50		ca. 1891	no style	2-story wood frame multi-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, aluminum clapboard siding, stone foundation, 3 entrance off of full porch w/ iron piers, double-hung windows, casement windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
3	West St	108.12-3-14	E.A. Merritt (1875)	ca. 1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior metal chimney pipe, vinyl clapboard siding, stone foundation, side hall entrance framed by pilasters & entablature w/ sidelights off of full porch w/ turned columns, double-hung windows, 1-story wood frame additions on south & off of rear northeast corner.
5	West St	108.12-3-14	J. Carpenter (1875)	1870	Gothic Revival	HOUSE: 2-story wood frame single-family dwelling, asphalt shingle cross-gable roof w/ gable dormers on north, side hall entrance w/ partial sidelights & fanlight off of porch w/ recessed columns & balustrades, wood clapboard siding, double-hung windows, 2-story tripartite bays w/ double-hung windows, secondary entrance w/ fanlight off of portico on north facade, lower story tripartite bay w/ double-hung windows & cornice brackets on north facade, cornice brackets. GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle shed roof, wood clapboard siding, sectional garage bay doors.
7	West St	108.12-3-15		1925	Bungalow/Craftsman	1-story, 2-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney & gable dormer, wood shingle siding on dormer & upper gable ends, vinyl clapboard siding on lower story, stucco sided foundation, roof extends over full porch w/ tapered vinyl clapboarded piers & kneewall, side hall entrance & picture window, shallow square bay window on south façade, double hung windows on north & south facades, roof extends on rear over porch.
8	West St	108.12-3-46	J. Bailey (1875)	ca. 1950	Colonial Revival	1-story brick masonry & wood frame single family-dwelling w/ attached garage, asphalt shingle gambrel roof w/ dormer, brick wall construction, wood shingle siding on attached garage & upper gable ends, stone foundation, center entrance, various casement windows, large sectional garage bay door, dwelling has undergone extension alterations & additions.
9	West St	108.12-3-19		1875	Classical Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, asbestos shingle siding, stone foundation, side-hall entrance, double-hung windows, 1-story rear addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
10	West St	108.12-3-45		1889	Queen Anne	<p>HOUSE: 2-story, 3-bay wood frame single-family house, asphalt shingle cross-gable roof w/ interior brick chimney, wood clapboard siding & fishscale pattern wood shingle siding on upper gable ends, stone foundation, double door side hall entrance off of veranda w/ turned columns, scroll sawn brackets & spandrels, 2 upper center bay balconies w/ turned columns & balustrades under gable overhang w/ half-round spindle screen, double-hung windows.</p> <p>CARRIAGE HOUSE: 2-story wood frame carriage barn, asphalt shingle front-gable roof w/ exterior brick chimney on rear, wood clapboard siding, sectional garage bay doors, recessed niche w/ turned columns & balustrades, half-round spindle screen in gable end.</p>
11	West St	108.12-3-20	D. Smith (1875)	1850	Greek Revival	1.5-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior concrete chimney & lower rear cross-gable, vinyl clapboard siding, stone foundation, side hall entrance, double-hung windows, eyebrow windows, 1-story rear addition.
12	West St	108.12-3-42	C.B. (1875)	1850	Greek Revival	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney, vinyl clapboard siding, stone foundation, side hall entrance, double-hung windows, 1-story rear lean-to addition.
13	West St	108.12-3-21		1960	Ranch	1-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ exterior concrete chimney, aluminum clapboard siding, concrete block foundation, side entrance off of front ell w/ paired casement windows, single & paired double-hung windows, basement garage w/ sectional door.
14	West St	108.12-3-41	F. Burtall (1875)	1850	Classical Revival	<p>HOUSE: 2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on south end, side hall entrance w/ partial sidelights off of full porch, aluminum clapboard siding, stone foundation, double-hung windows, large 1-story addition on south.</p> <p>GARAGE: 1-story, 1-bay concrete block masonry garage, asphalt shingle roof, sectional garage bay door.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
16	West St	108.12-3-34		1975	Ranch	<p>HOUSE: 1-story brick masonry & wood frame two-family dwelling asphalt shingle side-gable roof w/ exterior brick chimney on north end, aluminum clapboard siding, lower brick wall construction, stucco sided concrete block foundation, recessed center entrance w/ partial sidelights, single & paired double-hung windows, large picture window, basement garage on south end w/ 2 sectional garage bay doors.</p> <p>SHED: 1-story wood frame shed w/ vertical wood siding & center door.</p>
18	West St	108.12-3-33	J. Mackey (1875)	1860	Classical Revival	<p>HOUSE: 2-story wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, stone & brick foundations, side hall entrance off of enclosed full porch, double-hung windows, 2-story addition off of southwest corner w/ oriel window.</p> <p>GARAGE: 1-story, 1-bay concrete block masonry garage, asphalt shingle gable roof, concrete block construction, large sectional garage bay door.</p>
20	West St	108.12-3-30	J. Quimby (1875)	1850	Greek Revival	1.5-story, 5-bay wood frame single-family dwelling, asphalt shingle side gable roof w/ exterior brick chimney on north end, vinyl clapboard siding, stone foundation, primary entrance at south end of full façade porch, double-hung windows, an eyebrow window, later attached 1-bay garage on north end.
27	West St	108.12-4-12		1930	Cape Cod	1-story wood frame two-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney & gable dormers, vinyl clapboard siding, concrete foundation, off center entrance w/ gable overhang, double-hung windows, small 1-story wing on west w/ enclosed summer porch.
31	West St	108.12-4-14		1940	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on north end & lower cross gable ell on front, wood clapboard siding, stucco sided foundation, 2 entrances under extension of roof w/ double-hung & picture window on front façade, double-hung windows on south façade, large attached 1-bay garage w/ sectional bay door.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
98	West St	108.12-4-21.100	C.D. Brower (1875)	1840	Greek Revival	<p>HOUSE: Originally 2-story, 3-bay wood frame single-family house w/ asphalt shingle side-gable roof & side hall entrance w/ partial sidelights, later 2-story cross-gable addition w/ basement garage, vinyl clapboard siding, stone foundation, tripartite oriel window over garage, round arch double-hung window on upper gable ends on east & west.</p> <p>GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle front gable roof, vinyl clapboard siding, sectional garage bay door, short double-hung windows.</p>
1	Western Ave	108.12-3-9	KeyBank	1980	Commercial	1-story brick masonry commercial building, asphalt shingle complex roof, brick wall construction, concrete foundation, recessed corner entrance, recessed corner window on east, secondary entrance toward rear on east facade, roof extends on west side over banking drive-thru.
2	Western Ave	108.12-2-30	Drug Store (1900)	ca. 1900	Commercial	2-story wood frame commercial building, flat roof of unknown synthetic material, vinyl novelty siding, concrete foundation, central recessed entrance flanked by large plate glass windows, upper story grouped double-hung windows on front facade, small double-hung windows on east facade, secondary entrance & sectional garage bay door toward rear on east facade, cornice encased
4	Western Ave	108.12-2-31	Post Office (1900)	ca. 1900	Commercial	2-story, 4-bay wood frame commercial building, flat roof of unknown synthetic material, brick front facade, asbestos shingle siding on west facade, stone foundation, side entrance accessing upper story, store front w/ double door entrance flanked by large plate glass windows, double-hung windows on upper story & on west facade, brick corbels.
10	Western Ave	108.12-2-32	General Store/Insurance Office (1886)	ca. 1886	Commercial	2-story wood frame commercial building, asphalt shingle front gable roof w/ flat roof of unknown synthetic material, vinyl clapboard siding, composite shingle siding in upper gable end, brick veneer on lower half of front facade's lower story, storefront consists of two entrances for two separate businesses w/ large plate glass windows, double-hung windows on front facade's upper story, two entrances off of an upper story deck on west facade w/ double-hung windows.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
14	Western Ave	108.12-2-33	J. Dubois (1875)	ca. 1875	Commercial	3-story, 3-bay wood frame commercial building, Mansard roof w/ octagonal pattern synthetic shingles & dormers, vinyl clapboard siding, lower story concrete block construction on east façade, stone foundation, storefront w/ central recessed entrance flanked by large multi-pane windows under a shed rough overhang, arched recessed side entrance accessing upper stories, double-hung windows on upper stories.
15	Western Ave	108.12-3-6		1950	Commercial	2-story wood frame multi-family dwelling, asphalt shingle side-gable roof w/ lower rear cross-gable ell, lower story brick veneer & upper story vinyl clapboard siding, concrete foundation, two separate entrances off of full porch w/ iron piers & balustrades, double-hung windows.
16	Western Ave	108.12-2-34	J. Cropsy (1875)	ca. 1840	Queen Anne	2-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ lower rear cross-gable, side-hall entrance off of veranda w/ balustrades, turned columns & spandrels, double-hung windows, paired double-hung windows on upper story southwest corner, 1-story wood frame addition on northwest corner w/ entrance off north end of veranda.
19	Western Ave	108.12-3-6	Ice House (1886)	ca. 1886	Gothic Revival	2-story, wood frame single-family dwelling, asphalt shingle side-gable roof w/ center gable wall dormer, aluminum clapboard siding on upper story & brick veneer on lower story, stone foundation, side entrance & picture window on front facade's lower story, double-hung windows.
20	Western Ave	108.12-2-35	Candy, Cigar's & Ice Cream (1886)	ca. 1886	Commercial	2-story wood frame commercial building, low-pitched asphalt shingle gable roof vinyl clapboard siding, stone foundation, storefront w/ stone veneer, large plate glass windows & double-door side entrance, shed roof overhang supported by round columns, double-hung windows on upper story, cornice brackets & panels, 1-story rear brick additions.
22	Western Ave	108.12-2-36	Bakery	ca. 1886	Commercial	3-story, 5-bay wood frame commercial building, flat roof on unknown synthetic material, vinyl clapboard siding & brick veneer on lower story on front facade, stone foundation, lower story storefront consists of center entrance accessing upper stories & 2 separate businesses entrances w/ plate glass windows underneath asphalt shingle overhang, double-hung windows, gable roof line & double-hung windows underneath a reflection of early setback attached dwelling prior to building enlargement on east side, rear 2-story addition.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
24	Western Ave	108.12-2-38	Firehouse	1965	Commercial	2-story, 3-bay brick & concrete block masonry commercial building, flat roof of unknown synthetic material, brick wall constructed front façade & concrete block constructed east & rear facades, side door entrance w/ sectional garage bays doors & upper story double-hung windows on front façade, double-hung windows on east façade.
25	Western Ave	108.12-3-4		1960	Commercial	2-story wood frame & masonry commercial building, asphalt shingle side-gable roof w/ large center gable dormer, wood shingle siding & stone veneer, concrete foundation, roof extends over upper story porch, 2 sectional garage bay doors, 2 separate business entrances double-hung windows.
26	Western Ave	108.12-2-39	automobile dealership	ca. 1940	Commercial	BUILDING 1: 1 story, 3-bay brick masonry commercial building, flat roof of unknown synthetic material, brick wall construction, concrete foundation, sectional garage bay door flanked by large glass cube windows, low-stepped parapet wall. BUILDING 2: 1-story, 3-bay brick masonry & wood frame commercial building, asphalt shingle gable roof, brick wall construction on front facade, vinyl clapboard siding on upper gable end & on west facade, concrete foundation, center entrance flanked by large plate glass windows under awning,
29	Western Ave	108.12-3-3		1960	Commercial	1-story brick & concrete block masonry commercial building, asphalt shingle gable roof, brick wall construction on front & concrete block wall construction on rear, aluminum clapboard siding on upper gable end, storefront consists recessed corner entrance supported by brick pier on northeast w/ series of large plate glass windows.
30	Western Ave	108.12-2-40	C. Freer (1875)	1850	Queen Anne	2-story 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney & gable wall dormer, aluminum clapboard siding, stucco sided stone foundation, side hall entrance on exterior vestibule, double-hung windows, 2-story tripartite bay window on front of later 2-story addition w/ flat roof of unknown synthetic material on west, double-hung windows & grouped casement windows on west façade, oculus window on dormer, paired eave brackets, 1-story attached garage w/ sectional door & stone chimney on rear.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
31	Western Ave	108.12-3-2	W. Purmley (1875)	ca. 1875	Greek Revival	1-story, 2-bay wood frame multi-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, side hall entrance off of later portico w/ iron piers & railing, later paired double-hung windows, 2-story wood frame addition w/ low-pitched gable roof of southwest corner.
32	Western Ave	108.12-2-41		1900	no style	1-story wood frame single-family dwelling, low-pitched Asphalt shingle front-gable roof w/ exterior brick chimney, aluminum clapboard siding, brick & concrete foundation, side entrance, double-hung windows, large attached garage on southeast w/ sectional garage bay door,
33	Western Ave	108.12-3-2		1960	Commercial	1-story wood frame single-family dwelling, asphalt shingle front-gable roof, wood shingle siding on front facade w/ aluminum clapboard siding on upper gable end, side entrance w/ large multi-pane windows & double-hung windows on front facade.
34	Western Ave	108.12-2-42	F. Midden (1875)	ca. 1875	Greek Revival	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof, aluminum clapboard siding, stone foundation, center hall entrance off of later 3-bay wide porch w/ scroll sawn brackets & concrete block knee wall, 1-story lean-to rear & side additions.
35	Western Ave	108.12-3-2		1960	no style	1-story wood frame two-family dwelling, asphalt shingle side-gable roof, vertical wood paneling, concrete foundation, 2 separate entrances & single & paired double-hung windows on front facade, attached garage w/ sectional door.
36	Western Ave	108.12-2-43	J. Furlong (1875)	ca. 1875	no style	1-story wood frame single-family dwelling w/ large 2-story wood frame addition w/ flat roof to northwest, original dwelling w/ asphalt shingle side-gable roof, vinyl clapboard siding, stone & concrete foundations, later enclosed brick porch w/ side entrance & double-hung windows, small 1-story entrance on southeast, center entrance on northwest addition flanked by picture windows.
37	Western Ave	108.12-3-1		ca. 1850	Italianate	2-story, 3-bay wood frame single-family dwelling, pressed metal shingle side-gable roof w/ interior brick chimney, wood clapboard siding, stone foundation, side hall entrance off of later Colonial Revival style portico, double-hung windows, cornice brackets.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
39	Western Ave	108.12-1-15		ca. 1850	Queen Anne	<p>HOUSE: 2-story, 5-bay wood frame two-family dwelling, asphalt shingle side-gable roof w/ front cross-gable & interior brick chimneys on opposing ends, vinyl clapboard siding, brick foundation, center hall entrance w/ partial sidelights & transom off of Queen Anne style porch w/ turned columns, balustrades, spandrels & brackets, double-hung windows, later 2-story tripartite bays w/ single & paired double-hung windows, rear porch, enclosed rear stairwell.</p> <p>GARAGE: 1-story, 1-bay metal frame garage, low-pitched front-gable roof, metal siding, sectional garage bay door.</p>
40	Western Ave	108.12-2-45		1965	Commercial	1-story, 3-bay masonry commercial building, asphalt shingle side-gable roof, stucco sided masonry walls w/ vinyl clapboard siding in upper gable ends, off center entrance w/ large square pane windows on front facade, small wing on east w/ secondary entrance, side entrance & double-hng windows on west facade.
42	Western Ave	108.12-2-46		1910	Classical Revival	2-story, 5-bay wood frame multi-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, stucco sided stone foundation, side hall entrance under gable overhang, double-hung windows, side entrance toward rear on east façade, upper story bump out toward front on west façade, lower story rear entrance on west façade.
43	Western Ave	108.12-1-14	United States Post Office	1958	Commercial	1-story brick & concrete masonry single governmental building, flat roof of unknown material, concrete block construction w/ brick on front facade, side entrance w/ three large multi-pane windows on front facade, metal multi-pane windows on northwest & southeast facades, upward pitched roof over rear loading dock.
44	Western Ave	108.12-2-47		2016	Colonial Revival	2-story, 5-bay wood frame multi-family dwelling, Asphalt shingle side-gable roof w/ large center gable dormer flanked by smaller gable dormers, vinyl clapboard siding, concrete foundation, center entrance w/ partial sidelights off of gable portico, paired double-hung windows, Palladian window.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
45	Western Ave	108.12-1-13	M. Berrian (1875)	ca. 1875	Gothic Revival	2-story, 5-bay wood frame two-family dwelling, metal side-gable roof w/ gable wall dormers & interior brick chimneys on opposing ends, aluminum clapboard siding, stone foundation, center hall entrance framed by pilasters & entablature w/ partial sidelights & transom, 3-bay wide center porch w/ later iron piers & railings, double-hung windows, multi-pane diamond shaped window in upper dormer.
46	Western Ave	108.12-2-48		1965	Commercial	2-story, brick & concrete block masonry multi-family dwelling, asphalt shingle gable roof w/ exterior concrete chimney, concrete block construction w/ brick veneer on front facade, concrete foundation, side entrance w/ single & paired double-hung windows on front facade, side entrance along mid-point on east facade, double-hung windows on east & west facades.
47	Western Ave	108.12-1-12	telephone switching station	ca. 1950	Commercial	1-story, 3-bay brick & concrete block masonry telecommunications building, asphalt shingle side-gable roof w/ rear cross-gable addition, brick wall construction w/ rear concrete block addition, concrete foundation.
48	Western Ave	108.12-2-49	gas station	ca. 1950	Commercial	1-story, 2-bay banked brick & concrete masonry commercial garage, flat roof of unknown material, concrete block construction w/ brick front facade & vinyl clapboard siding on northwest, large sectional garage bay doors, side entrance, sliding windows on northwest, double-hung windows on southeast, large metal roadside "Gulf" service sign.
49	Western Ave	108.12-1-11	A. Bailey (1875)	ca. 1850	Classical Revival	HOUSE: 2-story, 3-bay wood frame single dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, stone foundation, side hall entrance w/ partial sidelights off of later full porch w/ vinyl clapboard knee walls & square columns, double-hung windows, 1-story wood frame addition on northwest. GARAGE: 1-story, 2-bay wood frame garage, low-pitched asphalt shingle front-gable roof, vinyl clapboard siding, sectional garage bay door & side entrance.
50	Western Ave	108.12-2-50	American Legion Viebey-Sutton Post	ca. 1920	Commercial	1-story, 3-bay wood frame building, asphalt shingle front-gable roof, composite shingle siding, concrete foundation, center entrance off gable portico flanked by double-hung windows, double-hung windows on east & west facades.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
51	Western Ave	108.12-1-10	Mrs. Bailey (1875)	ca. 1850	Classical Revival	2-story, 3-bay wood frame single dwelling, asphalt shingle side-gable roof w/ interior brick chimney on northwest end, wood clapboard siding, stone foundation, side hall entrance w/ sidelights off of later full porch w/ wood clapboard knee walls & square columns, double-hung windows, 1-story wood frame addition on northwest.
52	Western Ave	108.12-2-51.200	Mrs. Berrian (1875)	ca. 1860	Classical Revival	2-story, 3-bay wood frame single-family dwelling w/ attached 1-story wood frame garage on northwest, asphalt shingle side-gable roof w/ vented cupola, vinyl clapboard siding, stone foundation, side hall entrance off of a full porch w/ square columns, scroll sawn brackets, & balustrades, double-hung windows.
55	Western Ave	108.12-1-9	D. Mackey (1875)	ca. 1860	Classical Revival	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on northwest end, vinyl clapboard siding, stone foundation, center hall entrance off of a later porch, double-hung windows, small 1-story exterior vestibule entrance off southeast corner.
57	Western Ave	108.12-1-8		1952	Ranch	HOUSE: 1-story, 3-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ interior brick chimney, aluminum clapboard siding, concrete foundation, center entrance off of hip roof portico w/ iron piers & balustrades, grouped double-hung windows on front façade, rear addition. GARAGE: 1-story, wood frame garage, asphalt shingle hip-gable roof, sectional garage bay door & man door.
58	Western Ave	108.12-2-53	D. Berrian (1875)	1840	Classical Revival	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on northwest end, wood shingle siding w/ vinyl clapboard siding on upper gable ends, stone & concrete foundation, center hall entrance w/ partial sidelights & later picture windows on front façade, later basement garage w/ sectional door on southeast façade, rear enclosed porch w/ side entrance on northwest corner.
59	Western Ave	108.12-1-6		1960	Ranch	HOUSE: 1-story wood frame & brick masonry single-family dwelling, asphalt shingle side-gable w/ interior masonry chimney, vinyl clapboard siding & brick wall construction, entrance off of later deck & double-hung windows on front façade, double-hung windows on northwest & southeast facades, basement garage w/ sectional door. SHED: 1-story wood frame shed w/ asphalt shingle gambrel roof & wood paneling.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
62	Western Ave	108.12-2-61		1895	Classical Revival	2-story, 3-bay banked wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, center hall entrance off of gable roof porch, casement windows on lower story, double-hung windows on upper story & upper gable end.
63	Western Ave	108.12-1-4	Res C. Mackey (1875)	ca. 1875	Classical Revival	2-story wood frame two-family dwelling, asphalt shingle front-gable roof w/ lower cross-gable & interior brick chimney, composite & vinyl clapboard siding, brick & stone foundation, concrete foundation, walk-in side-hall entrance w/ sidelights, exterior vestibule side entrance & upper story entrance on west façade, upper entrance 1s on west façade accessing lower & upper stories, double-hung windows, addition on east & over entrance on front façade.
65	Western Ave	108.12-1-3.200		2001	Colonial Revival	2-story, 4-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, off center entrance w/ sidelights, single & grouped double-hung windows.
66	Western Ave	108.12-2-56	C. H. C. & E. Co.	1911	Commercial	1-story brick masonry single-family dwelling, converted commercial building, asphalt shingle side-gable roof & flat roof of unknown synthetic material, brick wall construction, stone foundation, entrance off of later shed roof porch & paired double-hung windows on front façade, single double-hung windows on southeast façade, sectional garage bay door w/ cast stone name & date plaque above.
67	Western Ave	108.12-1-3.100		2003	Colonial Revival	2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, off center entrance w/ sidelights off of full porch w/ columns & balustrades, single, paired & grouped double-hung windows, sectional garage bay doors on east end.
69	Western Ave	108.12-1-2		1900	Foursquare	2-story, 3-bay wood frame single-family dwelling, asphalt shingle hip-gable roof w/ hip-gable dormers, vinyl clapboard siding, concrete foundation, center hall entrance flanked off of enclosed full porch w/ brick foundation, single & paired double-hung windows, side entrance toward rear on west facade.
70	Western Ave	108.12-2-57		1945	Classical Revival	1-story, 3-bay wood frame single family dwelling, asphalt shingle front-gable roof w/ exterior chimney pipe, vinyl clapboard siding, concrete foundation, center entrance, double-hung entrance, rear walk-in basement.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
72	Western Ave	108.12-2-57		1945	Classical Revival	1-story, 3-bay wood frame single family dwelling, asphalt shingle front-gable roof w/ exterior chimney pipe, vinyl clapboard siding, concrete foundation, center entrance, double-hung entrance, rear walk-in basement.
73	Western Ave	108.12-1-1.200	C. Mackey (1875)	ca. 1875	no style	2-story wood frame single-family dwelling, asphalt shingle side gable roof, asbestos shingle siding, brick & stone foundation, north wing w/ exterior brick chimney, later enclosed center hall entrance on west facade, walk-in basement entrance on east facade under projecting upper story supported by concrete block wall, 1-story wood frame addition w/ concrete foundation off northeast corner, double-hung windows.
74	Western Ave	108.12-2-58		1930	no style	HOUSE 1: 2 story, 3-bay wood frame two family dwelling, asphalt shingle side-gable roof, vinyl clapboard siding, concrete foundation, center entrance off of portico, upper story entrance off of recessed porch under southeast corner, double-hung windows, HOUSE 2: 2-story, 2-bay wood frame single family dwelling, asphalt shingle side-gable roof w/ interior brick chimney on west end, vinyl clapboard siding, side hall entrance, double-hung windows.
76	Western Ave	108.12-2-59		1940	Bungalow/Craftsman	1-story wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney & gable dormer, vinyl clapboard siding, concrete foundation, side entrance off of enclosed full porch, double-hung windows on east & west facades, grouped double-hung windows on dormer, side entrance on east facade.
78	Western Ave	108.12-2-60		1950	Cape Cod	1-story, 3-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ interior brick chimney, vinyl clapboard siding, concrete foundation, center entrance on exterior vestibule entrance, single & grouped double-hung windows on front facade, double-hung windows on east & west facades.
80	Western Ave	108.12-2-60		1940	no style	2-story, 2-bay wood frame single-family dwelling, asphalt shingle cross-gable roof w/ exterior brick chimney, vinyl clapboard siding, concrete foundation, side entrance off of full porch, double-hung windows, attached garage on west w/ sectional door & man door, attached car port.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
85	Western Ave	108.2-6-17		1890	Gothic Revival	<p>HOUSE: 1-story, 4-bay wood frame two-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, roof extends over porch on east, previous matching corner porch on west now enclosed, paired double-hung windows on front facade, single double-hung windows on northwest & southeast facades, rear side entrances on opposing sides.</p> <p>GARAGE: 1-story, 1-bay wood frame garage, asphalt shingle gable roof, composite siding, sectional door.</p>
89	Western Ave	108.2-6-14.100		1917	Bungalow/Craftsman	<p>HOUSE: 1-story wood frame single-family dwelling, asphalt shingle hip-gable roof w/ interior cobble stone chimney & hip-gable dormers, stucco sided stone foundation, on northeast corner, entrance off of recessed porch w/ shingle sided piers & balustrades, single, paired & grouped double-hung windows, projecting corner bay w/ grouped double-hung windows on northwest, side entrance off of hip-gable portico toward rear on east façade.</p> <p>GARAGE: 1-story wood frame garage, asphalt shingle gable roof, wood shingle siding, sectional garage bay door, eave brackets, later attached car port.</p>
108	Western Ave	108.2-5-31	J. Clark (1853)	ca. 1853	Classical Revival	<p>1-story, 5-bay banked wood frame single-family house, asphalt shingle side-gable roof w/ exterior brick chimney on west end & center gable dormer, wood clapboard siding, stone foundation, center hall entrance w/ partial sidelights & transom framed by fluted pilasters off of 3-bay wide porch w/ square columns, spindle balustrades, spandrels & brackets, double-hung windows, walk-in basement entrance w/ double-hung windows, dormer sided w/ fishscale pattern wood shingles & large half round w/ double-hung windows, small 1-story brick wing on east.</p>

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
111-113	Western Ave	108.2-7-32.110	J. Clark & Saw Mill (1875)	ca. 1875	industrial	<p>HOUSE 1: 2-story banked wood frame single-family dwelling, asphalt shingle front-gable roof w/ interior brick chimney, vinyl clapboard siding, stone foundation, lean-to addition w/ concrete block foundation on north, side hall entrance off of wrap-around porch, double-hung windows.</p> <p>GARAGE: 1-story, 1-bay concrete block masonry garage, asphalt shingle front-gable roof, concrete block construction, wood novelty on upper gable ends, sectional garage door.</p> <p>HOUSE 2: 1-story banked wood frame two-family dwelling, converted saw mill, asphalt shingle side-gable roof w/ exterior concrete chimneys on east & west ends, wood clapboard siding, stone foundation, 2 entrances & double-hung windows on on front façade, side entrances on east & west ends w. double-hung windows, attached rear lean-to w/ open bays.</p> <p>BARN: 1-story. 4-bay concrete block masonry barn, asphalt shingle side-gable roof w/ exposed rafter ends, large rail track doors, side door & large multi-pane metal windows w/ concrete lintels on northwest façade.</p> <p>MACHINE SHED: 1-story wood frame machine shed, asphalt shingle side-gable roof, wood novelty siding, rail track doors & sectional bays doors on northeast façade, side entrance w/ double-hung windows on southeast end.</p>
112	Western Ave	108.2-5-32		1930	Bungalow/Craftsman	<p>HOUSE: 1-story wood frame single-family dwelling, asphalt shingle side gable roof w/ interior brick chimney on west end & shed dormer, wood shingle siding, stone foundation, roof extends over full screened-in porch w/ round columns & side entrance, secondary entrance on east facade, single double-hung windows, paired double-hung windows on dormers, single, paired, & grouped double-hung windows on west facade.</p> <p>GARAGE: 1-story, 2-bay wood frame garage, asphalt shingle front-gable roof, wood shingle siding, sectional garage bay doors, secondary entrance on west.</p>
115	Western Ave	108.2-7-31.200		1900	Colonial Revival	2-story wood frame single-family dwelling asphalt shingle cross-gable roof w/ gable wall dormers & exterior brick chimney on north end, vinyl clapboard siding, stucco sided foundation, off center primary entrance on front façade, double-hung windows, secondary entrance & tripartite bay w/ double-hung windows on south façade, paired double-hung windows in upper gable ends, porch on north end.

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
129-135	Western Ave	108.2-7-28	D. Decker (1875)	ca. 1875	Gothic Revival	<p>HOUSE: 2-story, 6-bay wood frame multi-family dwelling, asphalt shingle cross-gable roof w/ interior brick chimney & flat roof of unknown synthetic material on later 2-story north addition, vinyl clapboard siding, stucco sided stone foundation, original dwelling in center of mass denoted by front-gable roof & 3-bay wide porch, side hall entrance, double-hung windows.</p> <p>WORKSHOP: 1-story, 3-bay wood frame workshop, asphalt shingle side-gable roof, wood clapboard siding, center entrance under gable overhang, paired double-hung windows, single double-hung windows in upper gable ends.</p>
3	White St	108.12-2-52.100		1930	Bungalow/Craftsman industrial	<p>1-story, 2-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ gable dormer & exterior brick chimney on south side, wood clapboard siding & wood shingle on upper gable ends & dormer, concrete block foundation, roof extends over veranda w/ single & grouped tapered columns on brick piers & balustrades, side entrance w/ grouped double-hung windows on front façade, side entrance w/ paired double-hung windows & tripartite bay window on south façade, rear porch, eave brackets.</p> <p>MILL SITE</p>
	Willow Tree Rd	103.3-1-9	Hicksite Cemetery	ca. 1830		
18	Woodcrest Ln	103.3-3-24	J. Anderson (1858)	ca. 1840	Greek Revival	<p>HOUSE: 1.5-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof w/ exterior brick chimney on east end, vinyl clapboard siding, concrete & stone foundation, center hall entrance, double-hung windows, eyebrow windows, tripartite oriel window, small 1-story rear addition & porch.</p> <p>GARAGE: 1-story concrete block masonry garage, asphalt shingle gable roof, vinyl clapboard siding on upper gable ends, sectional garage bay door, double-hung windows.</p>
28	Woodcrest Ln	103.3-3-22	E.S. Wolsey (1875)	ca. 1875	Queen Anne	3-story, 6-bay wood frame multi-family dwelling, flat roof of unknown synthetic material, vinyl clapboard siding, stone foundation, paired center hall entrances w/ partial sidelights off of full veranda w/ turned columns, balustrades & scroll sawn brackets, double-hung windows.
73	Woodcrest Ln	103.3-3-16	P. Murray (1875)	1863		2-story, 5-bay wood frame single-family dwelling, asphalt shingle side-gable roof with dormers, stone and brick foundation, center-hall entrance, double-hung windows

TOWN OF MARLBOROUGH HAMLETS CULTURAL RESOURCE SURVEY

PROPERTY DATA

Street No.	Street Name	Parcel No.	Property Name/Type	Est. Year Built	Style	Description
23	Young Ave	109.1-3-3	Adams-Young House	1840		2-story, 5-bay brick masonry single-family dwelling, asphalt shingle side-gable roof, stone and brick foundation, center-hall entrance, double-hung windows
28	Young Ave	109.1-3-2	Lyons House	1963	Modernist	1-story banked wood frame single-family dwelling, flat roof of unknown synthetic material w/ interior brick chimney, wood clapboard siding, concrete foundation, entrance off of recess veranda w/ open roof light, sliding glass windows on all sides, large sliding glass windows & doors on rear looking out onto angled deck. Paul Canin, architect.