



EXISTING CONDITION
Photo 3: Milton Turnpike near #170



SIMULATED CONDITION
Photo 3: Milton Turnpike near #170
Distance to project: 710 Feet

Photograph Information

Date: September 24, 2024
Time: 2:00 PM
Focal Length: 50 mm
Photo Location: 41° 39' 54.7128" N, 73° 58' 22.0620" W

Project Specifications

PV Panel: 2 panel
Orientation: Portrait
Racking: Fixed Tile
Max Height: 15 feet
Fence: 8 foot Wood Post with Agricultural Fencing



SIMULATED CONDITION - With Landscape Mitigation (At Year 5)
Photo 3: Milton Turnpike near #170
Distance to project: 710 Feet

Photograph Information

Date: September 24, 2024
Time: 2:00 PM
Focal Length: 50 mm
Photo Location: 41° 39' 54.7128" N, 73° 58' 22.0620" W

Project Specifications

PV Panel: 2 panel
Orientation: Portrait
Racking: Fixed Tile
Max Height: 15 feet
Fence: 8 foot Wood Post with Agricultural Fencing



EXISTING CONDITION
Photo 4: South Road at Locust Grove Estate



SIMULATED CONDITION
Photo 4: South Road at Locust Grove Estate
Distance to project: 2.1 miles

Photograph Information

Date: September 24, 2024
Time: 3:30 PM
Focal Length: 50 mm
Photo Location: 41° 40' 24.0852" N, 73° 55' 55.4916" W

Project Specifications

PV Panel: 2 panel
Orientation: Portrait
Racking: Fixed Tile
Max Height: 15 feet
Fence: 8 foot Wood Post with Agricultural Fencing